



# Zigbee EmberZNet SDK 7.4.3.0 GA

## Gecko SDK Suite 4.4

### May 2, 2024

Silicon Labs is the vendor of choice for OEMs developing Zigbee networking into their products. The Silicon Labs Zigbee platform is the most integrated, complete, and feature-rich Zigbee solution available.

Silicon Labs EmberZNet SDK contains Silicon Labs' implementation of the Zigbee stack specification.

These release notes cover SDK version(s):

- 7.4.3.0 released May 2, 2024
- 7.4.2.0 released April 10, 2024
- 7.4.1.0 released February 14, 2024
- 7.4.0.0 released December 13, 2023



#### KEY FEATURES

##### Zigbee

- Zigbee R23 compliance
- Zigbee Smart Energy 1.4a compliance - production
- Zigbee GP 1.1.2 compliance - Alpha
- MG27 support - production
- Improved support for Secure Vault parts
- Sleepy support on NCP SPI (non-CPC) applications – Alpha

##### Multiprotocol

- Concurrent Listening support (RCP) – MG21 and MG24
- Concurrent Multiprotocol (CMP) Zigbee NCP + OpenThread RCP – production
- Dynamic Multiprotocol Bluetooth + Concurrent Multiprotocol (CMP) Zigbee and OpenThread support on SoC

## Compatibility and Use Notices

For information about security updates and notices, see the Security chapter of the Gecko Platform Release notes installed with this SDK or on the TECH DOCS tab on <https://www.silabs.com/developers/zigbee-emberznet>. Silicon Labs also strongly recommends that you subscribe to Security Advisories for up-to-date information. For instructions, or if you are new to the Zigbee EmberZNet SDK, see [Using This Release](#).

### Compatible Compilers:

IAR Embedded Workbench for ARM (IAR-EWARM) version 9.40.1.

- Using wine to build with the larBuild.exe command line utility or IAR Embedded Workbench GUI on macOS or Linux could result in incorrect files being used due to collisions in wine's hashing algorithm for generating short file names.
- Customers on macOS or Linux are advised not to build with IAR outside of Simplicity Studio. Customers who do should carefully verify that the correct files are being used.

GCC (The GNU Compiler Collection) version 12.2.1, provided with Simplicity Studio.

The EZSP protocol version for this release is 0x0D.

**Contents**

- 1 New Items ..... 3
  - 1.1 New Components ..... 3
  - 1.2 New APIs ..... 3
  - 1.3 New Platform Support ..... 4
  - 1.4 New Documentation ..... 4
  - 1.5 Intended Behavior ..... 4
- 2 Improvements ..... 5
- 3 Fixed Issues ..... 6
- 4 Known Issues in the Current Release ..... 10
- 5 Deprecated Items ..... 13
- 6 Removed Items ..... 14
- 7 Multiprotocol Gateway and RCP ..... 15
  - 7.1 New Items ..... 15
  - 7.2 Improvements ..... 15
  - 7.3 Fixed Issues ..... 15
  - 7.4 Known Issues in the Current Release ..... 16
  - 7.5 Deprecated Items ..... 16
  - 7.6 Removed Items ..... 16
- 8 Using This Release ..... 17
  - 8.1 Installation and Use ..... 17
  - 8.2 Security Information ..... 17
  - 8.3 Support ..... 18

# 1 New Items

This release of the Gecko SDK (GSDK) will be the last with combined support for all EFM and EFR devices, except for patches to this version as needed. Starting in mid-2024 we will introduce separate SDKs:

- The existing Gecko SDK will continue with support for Series 0 and 1 devices.
- A new SDK will cater specifically to Series 2 and 3 devices.

The Gecko SDK will continue to support all Series 0 and 1 devices with no change to the long-term support, maintenance, quality, and responsiveness provided under our software policy.

The new SDK will branch from Gecko SDK and begin to offer new features that help developers take advantage of the advanced capabilities of our Series 2 and 3 products.

This decision aligns with customer feedback, reflecting our commitment to elevate quality, ensure stability, and enhance performance for an exceptional user experience across our software SDKs.

## 1.1 New Components

### New in release 7.4.0.0

- The "zigbee\_direct\_security\_p256" and "zigbee\_direct\_security\_curve25519" components have been added so that users can configure a specific Zigbee Direct security option.

Users are allowed to have multiple "zigbee\_direct\_security" components enabled on a Zigbee direct device (ZDD) application. In this case, the actual security option depends on the Zigbee Virtual Device (ZVD) configuration.

## 1.2 New APIs

### New in release 7.4.2.0

- Extended SPI NCP to be used as sleepy in some Host-NCP use cases.  
In this use case the SPI NCP can be configured as a sleepy end device. The host Z3Gateway sample application is extended with additional custom CLI code responsible for commanding the NCP to enter one of the sleep modes through the custom CLI command sleepMode, and must wake up using the custom CLI command wakeup before further EZSP communication.
- Introduced a new API `sl_zigbee_af_isr_event_init` to initialize the application framework events that are intended to be activated inside an interrupt service routine (ISR). These events, which are scheduled from the ISR, must have a delay param of 0 milliseconds. In other words, events from ISR must be activated as an immediate event. There is no event deactivation allowed inside ISR.  
The reason for the above is as follows. The event system uses the event queue manipulation during scheduling (activating with a non zero delay, or deactivating) an event. To minimize the latency, an ISR should activate an event with 0 delay, that gets scheduled in the next event queue processing. This allows the further delay, or deactivation, to be carried out after ISR exits. To distinguish the events intended to be used inside ISR, the event structure is marked with an `sl_zigbee_isr_event_marker` during initialization.  
Refer to the `zigbee_app_framework_event.h` source file for details of this new function.
- Clarification on the use of the new function `emberUpdateMultiMacRejoinChannelMaskForSelectionOrJoiningDevice` that is called inside the stack API `emberFindAndRejoinNetworkWithReason` to get a channel mask used for rejoining.  
The SE1.4a specification restricts the change of interface (from 2.4GHz to sub-GHz or vice versa) during rejoining of a Multi-Mac Joining End device type device. Since the device type is an application framework configuration (that is, the joining end device type will be either a sub-GHz device or a 2.4 GHz device, not both, at configuration), this call provides the channel mask based on that configuration so that the rejoin mask is always same as the joining interface mask.

### New in release 7.4.0.0

- Added a new API `sl_zigbee_token_factory_reset` to reset Zigbee NVM3 tokens to their default value.
- Added the API `bool sl_zigbee_sec_man_link_key_slot_available(EmberEUI64 eui)`, which returns true if the link key table can add or update an entry with this address (table is not full).

Added a new API `bool sl_zb_sec_man_compare_key_to_value(sl_zb_sec_man_context_t* context, sl_zb_sec_man_key_t* key)`, which returns true if the key being referenced by context has the same value as the key supplied in the argument.

## 1.3 New Platform Support

### New in release 7.4.0.0

- Zigbee stack support for the following new parts is added in this release: EFR32MG24A010F768IM40 and EFR32MG24A020F768IM40.

## 1.4 New Documentation

### New in release 7.4.0.0

Updated the description for the Zigbee Secure Key Storage component to reflect the addition of Zigbee Secure Key Storage Upgrade (which adds backwards compatibility with existing projects).

Added a new application note for interacting with the Zigbee Security Manager group of components ([AN1412: Zigbee Security Manager](#)).

## 1.5 Intended Behavior

Users are reminded that Zigbee unsynchronized CSL transmissions are subject to protocol preemption at the radio scheduler. In the SleepyToSleepy applications, BLE can and will preempt a Zigbee CSL transmission, which will terminate the transmission. Scheduler preemption is more common for unsynchronized CSL, given that a potentially lengthy wake up frame sequence may be used. Users wishing to adjust transmission priorities may use the DMP Tuning and Testing component to do so. Users may also consult [UG305: Dynamic Multiprotocol User's Guide](#) for more information.

## 2 Improvements

### Changed in release 7.4.0.0

#### emberCounterHandler API Doc Changes

In previous versions, the Counter Handler callback for MAC and APS layer EmberCounterTypes concerning packet RX and TX was not being passed the passing proper target node ID or data arguments, and API documentation concerning behavior of certain counters that used these parameters was unclear or misleading.

While the signature of `emberCounterHandler()` has not changed, the way its parameters are populated have changed slightly.

- Comments around EmberCounterType enums in `ember-types.h` have been expanded for clarity.
- The Node ID parameter to the Counter Handler for TX-related counters now checks whether the destination address mode indicates a valid short ID before using it. (If not, no destination address is populated, and a placeholder value of `EMBER_UNKNOWN_NODE_ID` is used instead.)
- The Node ID parameter to the Counter Handler for RX-related counters now reflects the source node ID, not the destination node ID.
- Retry count is *not* passed as the data parameter for `EMBER_COUNTER_MAC_TX_UNICAST_SUCCESS/FAILED` counters as described in `ember-types.h` in previous versions, but this was never properly populated in previously released versions so its value in previous releases would always have been 0. This behavior has been clarified in the description of those EmberCounterTypes. However, the Retry count for APS layer retries continues to be populated in the data parameter for `EMBER_COUNTER_APS_TX_UNICAST_SUCCESS/FAILED` counter types, to be consistent with prior releases.
- All counters that populate the Node ID or data parameter for the callback have been audited to ensure they pass the expected data, address, or `EMBER_UNKNOWN_NODE_ID`, if a Node ID was expected but could not be obtained from the packet, as described in the revised `ember-types.h` documentation.
- The Counter handler for `EMBER_COUNTER_MAC_TX_UNICAST_RETRY` now correctly reflects the MAC layer destination node ID and number of retries in its Destination Node ID and data parameters.
- The Counter handler for `EMBER_COUNTER_PHY_CCA_FAIL_COUNT` now provides destination node ID information through the Node ID parameter about the intended MAC layer target of the message that failed transmission.

#### Updated Green Power Code

Green power server code is updated with various improvements including:

- Added more validation code for incoming commands with invalid endpoint when receiving on the GP server.
- Added code to handle the case when there is no more space to build green power messages.
- The sink now drops pairing configuration with action `remove pairing` in some cases per spec section A.3.5.2.4.1.
- The sink now saves the existing group list of an entry before removing when processing Pairing Configuration with action `extend`.
- The Translation query command returns “NOT FOUND” as the error code when the translation table is empty or the index is bigger than number of entries in the table.
- Changed the version of GP endpoint in some apps from 1 to 0.

Using CSMA in the GPDF Send function is restricted because Green Power Devices are minimal energy devices and do not use CSMA in most of the designs. Instead, the preferred design is to send out multiple packets using the same energy budget.

Removed the use of a hidden endpoint in the Green Power Server plugin option. Use one of the application endpoints instead.

#### Network Key Update Plugin Code Improvements

- Changed the periodic network key update period to be as long as 1 year.

#### Restructured Some APIs to Avoid Unnecessary Key Export

Made changes to favor the use of key contexts over plaintext key data.

- `sl_zigbee_send_security_challenge_request` now takes in an `sl_zb_sec_man_context_t` argument in place of `EmberKeyData`.
- The `sl_zb_sec_man_derived_key_type` enum's values are now a 16-bit bitmask to directly support certain key derivations that combine multiple derived types.

### 3 Fixed Issues

#### Fixed in release 7.4.2.0

ID #	Description
1252268	The zigbee host application option to open an IP port on 4900/4901 is deprecated. The alternative way to use a remote connection in order to interact with the host application may be to use the socat utility in most supported operating systems. (Other ref: 1232361)
1254541	A new event initialization function, <code>sl_zigbee_af_isr_event_init</code> , is introduced to allow the initialization of the application events intended to be activated from an interrupt service routine (ISR). These events can only be activated from the ISR with delay of 0 msec. These events shall not be scheduled with a non-zero delay or deactivated from within ISR.  The application framework documentation for the above function has been added. Please refer to <a href="https://docs.silabs.com">docs.silabs.com</a> for this release for the above API documents. (Other ref: 1252940)
1255175	Fixed issue that caused the APS Verify Key Confirm message processing error. (Other ref: 1227738)
1260605	Optional optionsMask parameter for "net multi-phy-start" CLI command was being ignored and always treated as 0. (Other ref: 1258636)
1262538	Fixed an issue that the GP server did not drop frame with FC equal to stored FC. (Other ref: 1259936)
1263124	Removed code for deprecated MAC command handling. (Other ref: 1262368)
1266765	Fixed an issue with the label of the pro leaf stack. (Other ref: 1259298)
1270706	Fixed an issue that prevented the application framework to send out ZCL default response for success case.
1272181	Fixed an issue that caused build failure when enabling expanded reporting table on Z3Gateway. (Other ref: 1188397)
1272280	The SE1.4a specification requires a Multi-MAC Joining End Device to rejoin on the same interface it has previously joined. No change of interface (switching from 2.4GHz to Sub-GHz or vice versa) is allowed during rejoining. The rejoin may be initiated as a result of parent loss or a power recycle of the node. In both of these cases, the stack API <code>emberFindAndRejoinNetworkWithReason</code> is called internally to start the rejoin process, and this API needs the rejoin channel mask as an argument. This channel mask is acquired by the stack by the calling function, <code>emberUpdateMultiMacRejoinChannelMaskForSelectionOrJoiningDevice</code> , that is implemented as source and as part of the application project.  A default implementation can be found in the <code>ember-configuration.c</code> as a WEAK function so that a user override is possible.
1273235	Triggering a child removal operation for a sleepy end device child when an Association Response or Rejoin Response is still pending delivery for that child can result in two erasures for the same child entry. This will leave the <code>emberChildCount()</code> off by -1. If this is the last child in the table to be removed, this can lead to an underflow of the child count. This inhibit any further join/rejoin attempts by any end devices until a reset or <code>LeaveNetwork</code> is performed, which may result in an assert failure (citing <code>child.c</code> ) in certain releases.
1273585	The initialization value for the green power security frame counters in non volatile memory is set to 0 from 0xFFFFFFFF. (Other ref: 1269700)
1277012	If the child table is full, and an existing child of the local device tries to rejoin, the rejoin is incorrectly rejected, causing the child entry to be removed and forcing the child to rejoin again to get reassocated with that parent.

**Fixed in release 7.4.1.0**

ID #	Description
1036893	Fixed an issue that caused the OTA cluster component installing the legacy boot-loader interface component as a dependency.
1114905	Zigbee Direct: Improved handling of Leave Network Characteristic.
1180937	Fixed WDT reset when connecting Zigbee Direct ZDD to 3rd party ZVD.
1223904	Fixed an issue that caused the end device move to work incorrectly in a very busy environment.
1224393	Updated the Green Power sink table request handler code to update the response destination address.
1228808	Fixed the display issue with macro definitions in gp-types.h documentation.
1232297	Fixed an issue where emberSetOutgoingNwkFrameCounter and emberSetOutgoingApsFrameCounter did not work on 64-bit host applications (returning EMBER_BAD_ARGUMENT).
1232359	Fixed the gppTunnelingDelay parameter calculation in green power client command processing.
1240392	ZDO Bind/Unbind Requests refused for access/permission reasons should return EMBER_ZDP_NOT_AUTHORIZED status rather than EMBER_ZDP_NOT_PERMITTED status as per Zigbee specifications.
1243523	Zigbee Direct: Improved stability of BLE connection to ZVD.
1249455	Fixed an issue that caused a sleepy end device to enter sleep when received a broadcast before receiving an ack.
1252295	Fix a typo error in component catalog macro SL_CATALOG_ZIGBEE_OTA_STORAGE_COMMON_PRESENT.

**Fixed in release 7.4.0.0**

ID #	Description
1019348	Fixed the dependency requirements for the Zigbee ZCL Cli component so that it can be removed when not needed.
1024246	Updated the function description for emberHaveLinkKey() and sl_zb_sec_man_have_link_key().
1036503	Added a description to recommend use of the Micrium Kernel for DMP sample apps.
1037661	An issue that was preventing the application to install either pro stack or leaf stack has been fixed.
1078136	Fixed an intermittent crash when modifying events from interrupt context
1081548	<p>Users are reminded that Zigbee unsynchronized CSL transmissions are subject to protocol preemption at the radio scheduler. In the SleepyToSleepy applications, BLE can and will preempt a Zigbee CSL transmission, which will terminate the transmission. Scheduler preemption is more common for unsynchronized CSL, given that a potentially lengthy wake up frame sequence may be used. Users wishing to adjust transmission priorities may use the DMP Tuning and Testing component to do so. Users may also consult UG305: Dynamic Multiprotocol User's Guide for more information.</p> <p>An issue has been fixed in CSL where a new wake up frame sequence that is received immediately following a previous payload frame would not be recorded correctly. This would result in a missed payload frame.</p>
1084111	Initial sleepy SPI-NCP support for MG24 based boards are updated as part of this release.
1104056	Added support for network-steering to run on secondary network in case of multi-network
1120515	Fixed an issue where the channel did not change when using the mfglib set-channel command.
1141109	Fixed an issue that caused the generated sample application ncp-uart-gp-multi-rail to miss some header files when using the Green Power adapter component with the -cp option.
1144316	Updated the description of some data structure types in gp-types.h documentation.
1144884	Fixed spurious frame pending bit set when there is no data pending.
1152512	Fixed a potential crash in low-mac-rail when modifying the event in isr context.
1154616	Added an exception for the condition to initialize the network with the case "Switching role from Sleepy End device to Non-sleepy End device".
1157289	Fixed an issue that may cause BDB test failure DN-TLM-TC-02B.

ID #	Description
1157426	Fixed a build issue when building zigbee_simple_app with green_power_adapter component.
1157932	Added a condition to check if the "transition time" field is missing and set a default value 0xFFFF for this missing field.
1166340	Fixed an issue that was preventing the emberAfGpdfSend from sending out the intended number of repeated transmissions.
1167807	Fixed an issue where devices acting as Trust Centers in distributed networks would incorrectly clear their transient link keys each time a new device joined.
1169504	Fixed an issue that caused reset of a sleepy device upon force wake up.
1169966	Fixed missing return value validation in buffer allocation code.
1171477, 172270	With mfglib start 1 no messages are transmitted but received, so the displayed terminal message "mfglib send complete" is wrong and changed to "RXed %d packets in the last %d ms".
1171935	Changed the periodic network key update period to be as long as 1 year.
1172778	Added the missing invocation of the emberAfPluginGreenPowerServerUpdateAliasCallback to the Green Power server..
1174288	Fixed an issue that causes the network steering process to assert if a call to stop ongoing scan is called.
1178393	Updated a documentation error.
1180445	In Smart Energy, OTA now continues to download if the Coordinator reaches Limited Duty Cycle.
1185509	Fixed an issue in CSL where a new wake up frame sequence that is received immediately following a previous payload frame would not be recorded correctly. This would result in a missed payload frame.
1186107	Fixed an issue that caused the unsuccessful decryption of received GPDFs to replace the incoming GPDF in the gp commissioning notification.
1188397	Fixed an issue that caused a compilation error when enabling extended report table size.
1194090	Corrected the failure status in the default response for Sink Commissioning Mode command - following section 3.3.4.8.2
1194963	Fixed an issue that memset the commissioningGpd structure before calling user callback emberAfGreenPowerServerPairingStatusCallback.
1194966	Fixed an issue where the endpoint and proxiesInvolved fields were not set with the Exit Commissioning action.
1196698	Fixed a spurious frame pending bit set when there was no data pending.
1199958	Added code to handle the case when there is no more space to build green power messages.
1202034	Fixed an issue where sl_zb_sec_man_context_t stack variable was not initialized correctly, causing joining with install code to fail.
1206040	Calling emberRemoveChild() during a secure rejoin attempt by an end device can potentially lead to an extra decrement of the Child Count, potentially leading to a Child Count of -1 (255), inhibiting end devices from joining/rejoining due to an indicated lack of capacity in the Beacon.
1207580	Child Table search functions within the stack are inconsistent in use of 0x0000 versus 0xFFFF for node ID return value representing invalid/empty entries, leading to problems checking for unused entries in APIs like emberRemoveChild().
1210706	Destination and PHY Index provided in EmberExtraCounterInfo struct as part of emberCounterHandler() may have been incorrect for MAC TX Unicast counter types.
1211610 1212525	Fixed an issue where Dynamic Multiprotocol applications crashed after enabling Secure Key Storage Upgrade component.
1211847	While the signature of emberCounterHandler() has not changed, the way its parameters are populated have changed slightly. Changes around this API is explained in section 2 above.
1212449	Outgoing Beacons were incorrectly categorized by the MAC layer, leading to emberCounterHandler() failing to catch these packets with the EMBER_COUNTER_MAC_TX_BROADCAST counter type and instead counting the Beacons with the EMBER_COUNTER_MAC_TX_UNICAST_SUCCESS counter type. That potentially resulted in unreliable values for the dest EmberNodeId parameter passed to the EmberCounterInfo struct
1214866	Sending data poll packet in certain high traffic configurations may result in a bus fault.
1216552	An issue that causes an assertion under busy traffic conditions is fixed.
1216613	Fixed an issue which led to an incorrect value of groupcast radius in the proxy table.



ID #	Description
1222509	Router/coordinator sends a leave & rejoin request to a non-child polling end device, but the MAC destination is 0xFFFF instead of matching the NWK destination address.
1223842	Fixed an issue with generation of the sl_component_catalog.h that was leaving unwanted code in it causing compilation failure.
756628	Changed the invocation of application callback emberAfMacFilterMatchMessageCallback to only be called for the ZLL messages that are validated by the stack.
816088	Moved EMBER configuration from zigbeed_configuration.h to zigbeed.scp.
829508	To avoid a race condition, additional validation was added in emberSetLogicalAndRadioChannel to return unsuccessful if the lower layers are busy or not in a state to change the channel.

## 4 Known Issues in the Current Release

Issues in bold were added since the previous release. If you have missed a release, recent release notes are available on <https://www.silabs.com/developers/zigbee-emberznet> in the Tech Docs tab.

ID #	Description	Workaround
N/A	The following apps/component is not supported in this release: EM4 support.	Feature will be enabled in subsequent releases.
193492	emberAfFillCommandGlobalServerToClientConfigureReporting macro is broken. The filling of buffer creates incorrect command packet.	Use the "zcl global send-me-a-report" CLI command instead of the API.
278063	Smart Energy Tunneling plugins have conflicting treatment/usage of address table index.	No known workaround
289569	Network-creator component power level picklist doesn't offer full range of supported values for EFR32	Edit the range <-8..20> specified in the CMSIS comment for EMBER_AF_PLUGIN_NETWORK_CREATOR_RADIO_POWER in the <sdk>/protocol/zigbee/app/framework/plugin/network-creator/config/network-creator-config.h file. For example, change to <-26..20>.
295498	UART reception sometimes drops bytes under heavy load in Zigbee+BLE dynamic multiprotocol use case.	Use hardware flow control or lower the baud rate.
312291	EMHAL: The halCommonGetIntxxMillisecondTick functions on Linux hosts currently use the gettimeofday function, which is not guaranteed to be monotonic. If the system time changes, it can cause issues with stack timing.	Modify these functions to use clock_gettime with the CLOCK_MONOTONIC source instead.
338151	Initializing NCP with a low packet buffer count value may cause corrupt packets.	Use the 0xFF reserved value for packet buffer count to avoid the too-low default value
387750	Issue with Route Table Request formats on end device.	Under Investigation
400418	A touchlink initiator cannot link to a non-factory-new end-device target.	No known workaround.
424355	A non-factory-new sleepy end device touchlink target-capable initiator is not able to receive a device information response in certain circumstances.	Under Investigation
465180	The Coexistence Radio Blocker Optimization item "Enable Runtime Control" may block proper Zigbee operation.	Optional 'Wi-Fi Select' Control of Blocker Optimization should be left "Disabled".
480550	The OTA cluster has its own built-in fragmentation method, hence it should not use APS fragmentation. Although, in case APS encryption is enabled it grows the payload of the ImageBlockResponses to a size where the APS fragmentation is activated. This could lead to the OTA process failing.	No known workaround
481128	Detailed Reset Cause and crash details should be available by default via the Virtual UART (Serial 0) on NCP platforms when Diagnostics plugin and Virtual UART peripheral are enabled.	Since Serial 0 is already initialized in the NCP, customers can enable the emberAfNcpInitCallback in the Zigbee NCP Framework and call the appropriate diagnostic functions (halGetExtendedResetInfo, halGetExtendedResetString, halPrintCrashSummary, halPrintCrashDetails, and halPrintCrashData) in this callback to print this data to Serial 0 for viewing in the Network Analyzer capture log. For an example of how to use these functions, refer to the code included in af-main-soc.c's emberAfMainInit() when EXTENDED_RESET_INFO is defined.

ID #	Description	Workaround
486369	If a DynamicMultiProtocolLightSoc forming a new network has child nodes remaining from a network it has left, emberAfGetChildTableSize returns a non-zero value in startIdentifyOnAllChildNodes, causing Tx 66 error messages when addressing the "ghost" children.	Mass-erase the part if possible before creating a new network or programmatically check the child table after leaving the network and delete all children using emberRemoveChild prior to forming a new network.
495563	Joining SPI NCP Sleepy End Device Sample App doesn't short poll, therefore the joining attempt fails at the state of Update TC Link Key.	The device that wishes to join should be in Short Poll mode before attempting to join. This mode can be forced by the End Device Support plugin.
497832	In Network Analyzer the Zigbee Application Support Command Breakdown for the Verify Key Request Frame mistakenly references the part of the payload that indicates the frame Source Address as the Destination Address.	No known workaround
519905 521782	Spi-NCP may very rarely fail to start up bootloader communication using the 'bootload' CLI command of the ota-client plugin.	Restart the bootload process
620596	NCP SPI Example for BRD4181A (EFR32xGMG21) nWake default pin defined cannot be used as a wake-up pin.	Change the default pin for nWake from PD03 to a EM2/3 wake-up-enabled pin in the NCP-SPI Plugin.
631713	A Zigbee End Device will report address conflicts repeatedly if the plugin "Zigbee PRO Stack Library" is used instead of "Zigbee PRO Leaf Library".	Use the "Zigbee PRO Leaf Library" instead of the "Zigbee PRO Stack Library" plugin.
670702	Inefficiencies within the Reporting plugin can lead to significant latency based on data write frequency and table size, which may interfere with customer application code, including event timing.	If doing frequent writes, consider checking reporting conditions and sending reports manually rather than using the plugin.
708258	Uninitialized value in groups-server.c via addEntryToGroupTable() can create a spurious binding and cause groupcast reporting messages to be sent.	Add "binding.clusterId = EMBER_AF_INVALID_CLUSTER_ID;" after "binding.type = EMBER_MULTICAST_BINDING;"
757775	All EFR32 parts have a unique RSSI offset. In addition, board design, antennas and enclosure can impact RSSI.	When creating a new project, install the RAIL Utility, RSSI component. This feature includes the default RSSI Offset Silabs has measured for each part. This offset can be modified if necessary after RF testing of your complete product.
758965	ZCL cluster components and ZCL command discovery table are not synchronized. Therefore, when enabling or disabling a ZCL cluster component, implemented commands will not be enabled/disabled in the corresponding ZCL Advanced Configurator command tab.	Manually enable/disable discovery for the desired ZCL commands in the ZCL Advanced Configurator.
765735	The OTA update fails on Sleepy End Device with enabled Page Request.	Use Block Request instead of Page Request.
845649	Removing CLI:Core component does not eliminate EEPROM cli calls to sl_cli.h.	Delete the eeprom-cli.c file that calls the sl_cli.h. Additionally, calls to sl_cli.h as well as sl_cli_command_arg_t in the ota-storage-simple-eeeprom can be commented out.
857200	ias-zone-server.c allows for a binding to be created with a "0000000000000000" CIE address and posteriorly does not allow further bindings.	No known workaround
1019961	Generated Z3Gateway makefile hardcodes "gcc" as CC	No known workaround

ID #	Description	Workaround
1039767	Zigbee router network retry queue overflow issue in multi thread RTOS use case.	Zigbee Stack is not thread-safe. As a result, calling Zigbee stack APIs from another task is not supported in OS environment and may put the stack into "non-working" state. Refer to the following App note for more information and workaround using event handler. <a href="https://www.silabs.com/documents/public/application-notes/an1322-dynamic-multiprotocol-bluetooth-zigbee-sdk-7x.pdf">https://www.silabs.com/documents/public/application-notes/an1322-dynamic-multiprotocol-bluetooth-zigbee-sdk-7x.pdf</a> .
1064370	The Z3Switch sample application only enabled one button (instance : btn1) by default that leads to mismatch in button description in the projectfile.	Workaround: Install the btn0 instance manually during Z3Switch project creation.
1161063	Z3Light and potentially other applications report incorrect cluster revision values.	Manually update the cluster revision attribute to their appropriate revision.
1164768, 1171478, 1171479	ERROR: ezspErrorHandler 0x34 reported repeatedly during mfglib receive mode	To reduce the error messages printed, configure EMBER_AF_PLUGIN_GATEWAY_MAX_WAIT_FOR_EVENT_TIMEOUT_MS on the host app to 100, so the callback queue is freed more quickly.
1252460	<b>SimEEPROM recovery routines (for both v1 and v2) run at startup may perform mis-aligned flash page erase call resulting in assert during em_msc.c's MSC_ErasePage routine.</b>	<b>Workaround: Place the following line of code at the top of the MSC_ErasePage() function in em_msc.c:</b> <code>startAddress = (uint32_t*)((uint32_t)startAddress &amp; ~(FLASH_PAGE_SIZE-1));</code>

## 5 Deprecated Items

### Deprecated in release 7.4.1.0

In GSDK 7.4.0.0 onwards, including this patch, the “-v” option in a Z3Gateway for a linux host application to create a telnet interface with port 4900 or 4901 is deprecated. The alternative recommended way to create a telnet interface is to use linux utilities such as “socat”.

### Deprecated in release 7.4.0.0

Removed the following deprecated security APIs:

```
emberGetKey()  
emberGetKeyTableEntry()  
emberSetKeyTableEntry()  
emberHaveLinkKey()  
emberAddOrUpdateKeyTableEntry()  
emberAddTransientLinkKey()  
emberGetTransientKeyTableEntry()  
emberGetTransientLinkKey()  
emberHmacAesHash()
```

Use the APIs provided by Zigbee Security Manager for access to key storage and HMAC hashing.

## 6 Removed Items

### Removed in release 7.4.0.0

- Removed duplicate public APIs in public header file gp-types.h.
- The zigbee\_end\_device\_bind component has been removed. This component was used for the coordinator to broker binding requests for end devices. This optional functionality was removed from R22 of the Zigbee core spec.
- Removed setPacketBufferCount() in af-host.c and useless check case EZSP\_CONFIG\_PACKET\_BUFFER\_COUNT: in command-handlers.c.
- Removed memoryAllocation argument because there is no need to divide into two phases when initializing NCP.
- Removed emberAfNcpInitCallback() in se14-comms-hub, se14-ihd, and se14-meter-gas 's app.c.
- Removed setting EZSP\_CONFIG\_RETRY\_QUEUE\_SIZE value during ncp initialization in ncp-configuration.c.

## 7 Multiprotocol Gateway and RCP

### 7.1 New Items

#### **Added in release 7.4.0.0**

Concurrent listening, the ability for the Zigbee and OpenThread stacks to operate on independent 802.15.4 channels when using an EFR32xG24 or xG21 RCP, is released. Concurrent listening is not available for the 802.15.4 RCP/Bluetooth RCP combination, the Zigbee NCP/OpenThread RCP combination, or for the Zigbee/OpenThread system-on-chip (SoC). It will be added to those products in a future release.

The OpenThread CLI vendor extension has been added to the OpenThread host apps of multiprotocol containers. This includes the `coex cli` commands.

### 7.2 Improvements

#### **Changed in release 7.4.0.0**

The Zigbee NCP/OpenThread RCP multiprotocol combination is now production quality.

### 7.3 Fixed Issues

#### **Fixed in release 7.4.2.0**

ID #	Description
1022972	Added coexistence plugin back to Zigbee-OpenThread NCP/RCP sample application.
1231021	Avoid an assert in OTBR that has been observed when joining 80+ zigbee devices by recovering the RCP rather than by passing unhandled transmit errors to the sub mac.
1249346	Addressed an issue where the RCP could incorrectly dequeue packets destined for the host, resulting in a parse error in the OTBR and unexpected termination.

#### **Fixed in release 7.4.1.0**

ID #	Description
1213701	zigbeed didn't allow a source match table entry to be created for a child if MAC indirect queue has data already pending for that child. This behavior could lead to application layer transactions between the child and some other device failing due to lack of APS Ack or app-layer response, most notably the disruption and unexpected termination of ZCL OTA Upgrades targeting the child device.
1244461	Source match table entry for child being could be removed despite messages pending.

#### **Fixed in release 7.4.0.0**

ID #	Description
1081828	Throughput issue with FreeRTOS-based Zigbee/BLE DMP sample applications.
1090921	Z3GatewayCpc had trouble forming a network in a noisy environment.
1153055	An assert on the host was caused when there was a communication failure when reading the NCP version from the zigbee_ncp-ble_ncp-uart sample app.
1155676	The 802.15.4 RCP discarded all received unicast packets (after MAC acking) if multiple 15.4 interfaces shared the same 16-bit node ID.
1173178	The host falsely reported hundreds of packets received with mfglib in the Host-RCP setup.

ID #	Description
1190859	EZSP error when sending mfglib random packets in the Host-RCP setup.
1199706	Data polls from forgotten end device children were not properly setting a pending frame on the RCP to queue a Leave & Rejoin command to the former child.
1207967	The "mfglib send random" command was sending out extra packets on Zigbeed.
1208012	The mfglib rx mode did not update packet info correctly when receiving on the RCP.
1214359	The coordinator node crashed when 80 or more routers tried to join simultaneously in the Host-RCP setup.
1216470	After relaying a broadcast for address mask 0xFFFF, a Zigbee RCP acting as a parent device would leave the pending data flag set for each child. This resulted in each child staying awake expecting data after each poll, and required some other pending data transaction to each end device to eventually clear this state.

## 7.4 Known Issues in the Current Release

Issues in bold were added since the previous release. If you have missed a release, recent release notes are available on <https://www.silabs.com/developers/gecko-software-development-kit>.

ID #	Description	Workaround
937562	Bluetoothctl 'advertise on' command fails with rcp-uart-802154-blehci app on Raspberry Pi OS 11.	Use btmgmt app instead of bluetoothctl.
1074205	The CMP RCP does not support two networks on the same PAN id.	Use different PAN ids for each network. Support is planned in a future release.
1122723	In a busy environment the CLI may become unresponsive in the z3-light_ot-ftd_soc app.	No known workaround.
1124140	z3-light_ot-ftd_soc sample app is not able to form the Zigbee network if the OT network is up already.	Start the Zigbee network first and the OT network after.
1170052	CMP Zigbee NCP + OT RCP and DMP Zigbee NCP + BLE NCP may not fit on 64KB and lower RAM parts in this current release.	64KB parts not currently supported for these apps.
1209958	The ZB/OT/BLE RCP on Bobcat and Bobcat Lite can stop working after a few minutes when running all three protocols	Will be addressed in a future release
1221299	Mfglib RSSI readings differ between RCP and NCP.	Will be addressed in a future release.

## 7.5 Deprecated Items

None

## 7.6 Removed Items

### Removed in release 7.4.0.0

The "NONCOMPLIANT\_ACK\_TIMING\_WORKAROUND" macro has been removed. All RCP apps now by default support 192  $\mu$ sec turnaround time for non-enhanced acks while still using 256  $\mu$ sec turnaround time for enhanced acks required by CSL.



## 8 Using This Release

This release contains the following:

- Zigbee stack
- Zigbee Application Framework
- Zigbee Sample Applications

For more information about Zigbee and the EmberZNet SDK see [UG103.02: Zigbee Fundamentals](#).

If you are a first-time user, see [QSG180: Zigbee EmberZNet Quick-Start Guide for SDK 7.0 and Higher](#), for instructions on configuring your development environment, building and flashing a sample application, and documentation references pointing to next steps.

### 8.1 Installation and Use

The Zigbee EmberZNet SDK is provided as part of the Gecko SDK (GSDK), the suite of Silicon Labs SDKs. To quickly get started with the GSDK, install [Simplicity Studio 5](#), which will set up your development environment and walk you through GSDK installation. Simplicity Studio 5 includes everything needed for IoT product development with Silicon Labs devices, including a resource and project launcher, software configuration tools, full IDE with GNU toolchain, and analysis tools. Installation instructions are provided in the online [Simplicity Studio 5 User's Guide](#).

Alternatively, Gecko SDK may be installed manually by downloading or cloning the latest from GitHub. See [https://github.com/SiliconLabs/gecko\\_sdk](https://github.com/SiliconLabs/gecko_sdk) for more information.

Simplicity Studio installs the GSDK by default in:

- (Windows): C:\Users\<<NAME>\SimplicityStudio\SDKs\gecko\_sdk
- (MacOS): /Users/<NAME>/SimplicityStudio/SDKs/gecko\_sdk

Documentation specific to the SDK version is installed with the SDK. Additional information can often be found in the [knowledge base articles \(KBAs\)](#). API references and other information about this and earlier releases is available on <https://docs.silabs.com/>.

### 8.2 Security Information

#### Secure Vault Integration

For applications that choose to store keys securely using the Secure Key Storage component on Secure Vault-High parts, the following table shows the protected keys and their storage protection characteristics that the Zigbee Security Manager component manages.

Wrapped Key	Exportable / Non-Exportable	Notes
Network Key	Exportable	
Trust Center Link Key	Exportable	
Transient Link Key	Exportable	Indexed key table, stored as volatile key
Application Link Key	Exportable	Indexed key table
Secure EZSP Key	Exportable	
ZLL Encryption Key	Exportable	
ZLL Preconfigured Key	Exportable	
GPD Proxy Key	Exportable	Indexed key table
GPD Sink Key	Exportable	Indexed key table
Internal/Placeholder Key	Exportable	Internal key for use by Zigbee Security Manager

Wrapped keys that are marked as “Non-Exportable” can be used but cannot be viewed or shared at runtime.

Wrapped keys that are marked as “Exportable” can be used or shared at runtime but remain encrypted while stored in flash.

User applications never need to interact with the majority of these keys. Existing APIs to manage Link Key Table keys or Transient Keys are still available to the user application and now route through the Zigbee Security Manager component.

Some of these keys may become non-exportable to the user application in the future. User applications are encouraged to not rely on the exporting of keys unless absolutely necessary.

For more information on Secure Vault Key Management functionality, see [AN1271: Secure Key Storage](#).

## Security Advisories

To subscribe to Security Advisories, log in to the Silicon Labs customer portal, then select **Account Home**. Click **HOME** to go to the portal home page and then click the **Manage Notifications** tile. Make sure that 'Software/Security Advisory Notices & Product Change Notices (PCNs)' is checked, and that you are subscribed at minimum for your platform and protocol. Click **Save** to save any changes.

The screenshot shows the 'Update Preference' page in the Silicon Labs customer portal. The page is titled 'Update Preference' and has a search bar at the top. Below the search bar, there are navigation links for 'HOME', 'CASES', and 'SOFTWARE RELEASES'. The main content area is divided into two sections: 'WHAT EMAILS WOULD YOU LIKE TO RECEIVE?' and 'SELECT THE PRODUCTS TO RECEIVE UPDATES FOR'.

In the 'WHAT EMAILS WOULD YOU LIKE TO RECEIVE?' section, there are several checkboxes under 'Newsletters' and 'Product Specific Notifications'. The checkbox for 'Software/Security Advisory Notices & Product Change Notices (PCNs)' is checked and highlighted with a red box. Other checkboxes include 'Community Monthly Newsletter', 'Sales Newsletter', 'Micrium Newsletter', 'Product Information and Newsletter', and 'Technical Document Updates (Release Notes, Data Sheets, etc.)'.

In the 'SELECT THE PRODUCTS TO RECEIVE UPDATES FOR' section, there are several checkboxes for different product categories. The '32-bit MCUs' checkbox is checked and highlighted with a red box. Other checkboxes include '8-bit MCUs', 'Timing', 'Clocks', 'Buffers', 'Oscillators', 'CDR and PHY', 'Audio and Radio', 'Interface', 'Isolation', 'Modems and DAAs', 'Microcontrollers', 'Voice', 'Wireless', 'Bluetooth Classic', 'Bluetooth Low Energy', 'Proprietary', 'Wi-Fi', 'ZigBee and Thread', 'Power over Ethernet', 'Sensors', and 'TV and Video'.

## 8.3 Support

Development Kit customers are eligible for training and technical support. Use the [Silicon Laboratories Zigbee web page](#) to obtain information about all Silicon Labs Zigbee products and services, and to sign up for product support.

You can contact Silicon Laboratories support at <http://www.silabs.com/support>.

# Simplicity Studio


One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



**IoT Portfolio**  
[www.silabs.com/IoT](http://www.silabs.com/IoT)



**SW/HW**  
[www.silabs.com/simplicity](http://www.silabs.com/simplicity)



**Quality**  
[www.silabs.com/quality](http://www.silabs.com/quality)



**Support & Community**  
[www.silabs.com/community](http://www.silabs.com/community)

## Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

**Note: This content may contain offensive terminology that is now obsolete. Silicon Labs is replacing these terms with inclusive language wherever possible. For more information, visit [www.silabs.com/about-us/inclusive-lexicon-project](http://www.silabs.com/about-us/inclusive-lexicon-project)**

## Trademark Information

Silicon Laboratories Inc.<sup>®</sup>, Silicon Laboratories<sup>®</sup>, Silicon Labs<sup>®</sup>, SiLabs<sup>®</sup> and the Silicon Labs logo<sup>®</sup>, Bluegiga<sup>®</sup>, Bluegiga Logo<sup>®</sup>, EFM<sup>®</sup>, EFM32<sup>®</sup>, EFR, Ember<sup>®</sup>, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals<sup>®</sup>, WiSeConnect, n-Link, ThreadArch<sup>®</sup>, EZLink<sup>®</sup>, EZRadio<sup>®</sup>, EZRadioPRO<sup>®</sup>, Gecko<sup>®</sup>, Gecko OS, Gecko OS Studio, Precision32<sup>®</sup>, Simplicity Studio<sup>®</sup>, Telegesis, the Telegesis Logo<sup>®</sup>, USBXpress<sup>®</sup>, Zentri, the Zentri logo and Zentri DMS, Z-Wave<sup>®</sup>, and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.  
400 West Cesar Chavez  
Austin, TX 78701  
USA

[www.silabs.com](http://www.silabs.com)