



EFR32 Mighty Gecko Family

EFR32MG1 with Integrated Serial Flash

Errata History



This document contains the errata history for EFR32MG1 with Integrated Serial Flash devices.

For errata on latest revision, please refer to the errata for the device. The device data sheet explains how to identify chip revision, either from package marking or electronically.

Errata history effective date: November 11th, 2016.

1. Errata Summary

Table 1.1. Errata History Overview

Designator	Title/Problem	Exists on Revision:
		C
ADC_E202	Wait After POR or EM4S Wakeup	X
ADC_E206	PROGERRIF (Program Error Interrupt Flag) Will Not Clear	X
ADC_E207	ADC Scan Repeat Mode with APORT	X
ADC_E208	ADC Interrupt Flags	X
ADC_E209	ADC and PRS Triggers	X
ADC_E210	ADC with PRS and Software Triggers	X
ADC_E211	ADC Single Repeat Mode and Tailgating	X
ADC_E212	ADC with PRS in ASYNC Mode	X
ADC_E213	ADC KEEPINSLOWACC Mode	X
ADC_E214	Using ADC CHCONMODE with PRS	X
ADC_E215	ADC CHCONMODE Set to MAXRESP Causes Extra Latency	X
ADC_E216	ADC Conversion Start Delay	X
ADC_E217	Multiple CLK Mode Switches	X
ADC_E218	SINGLEACT and SCANACT Status Flags Delayed	X
ADC_E219	STOP Command Causing FIFO Corruption	X
ADC_E220	AUXHFRCO in ASYNC mode with ASYNC CLK in ASNEEDED mode	X
ADC_E221	ADC Temperature Sensor Must be Used in LOWACC Mode	X
ADC_E222	ADC EM2 Wakeup on a Comparator Match Disables EM2 Entry	X
ADC_E223	Delayed ADC Conversion or Warmup Start	X
CORE_E201	SYSTICK and an External Clock	X
DBG_E201	AUXHFRCO Debug Limitations	X
DBG_E202	Debug Access to ADC and LEUART not Functioning as Intended	X
DCDC_E202	Regulated DCDC Output Can Dip on EM2 Entry	X
DCDC_E203	Regulated DCDC Output Can Dip on EM2 Entry if not in LN Mode	X
EFR_E201	Bit Access Not Supported for Low Energy Peripherals	X
EFR_E202	Read-Clear Access for LETIMER0 and RTCC Interrupts	X
EMU_E201	High Temperature Operation	X
EMU_E204	Restrictions Writing TEMPHIGH and TEMPLOW	X
EMU_E205	Restrictions Reading TEMP	X
EMU_E207	GPIO State can be Lost During EM4 Recovery	X
EMU_E208	Occasional Full Reset After Exiting EM4H	X
EMU_E209	Potential EM2 Lock-up when using IDAC or the Debugger with the LDMA	X
EMU_E210	Potential Power-Down When Entering EM2	X

Designator	Title/Problem	Exists on Revision:
		C
FLASH_E201	Potential Program Failure after Power On	X
I2C_E201	I2C ABORT Command	X
IDAC_E201	IDAC CURSTABLE Bit Not Reliable	X
LEUART_E201	Restrictions Setting TXDMAWU/RXDMAWU of LEUARTn_CTRL	X
RADIO_E202	802.15.4 Channel 14	X
RADIO_E203	Bluetooth Smart Channel 26	X
RADIO_E204	Increased EVM on Selected Channels	X
RMU_E201	CTRL Register Reset on All Resets	X
RTCC_E201	RTCC Does Not Support Compare/Capture Wrap with Prescaler	X
RTCC_E202	RTCC Triggers to LETIMER Not Safe	X
TIMER_E201	Timer in Input Capture Mode Can Stop Counting	X

Table 1.2. Errata Status Summary

Errata #	Designator	Title/Problem	Workaround	Affected	Resolution
			Exists	Revision	
1	RADIO_E202	802.15.4 Channel 14	No	C	Documented in the revision 1.0 data sheet
2	RADIO_E203	Bluetooth Smart Channel 26	No	C	Documented in the revision 1.0 data sheet
3	RADIO_E204	Increased EVM on Selected Channels	No	C	Documented in the revision 1.0 data sheet

2. Detailed Errata Descriptions

2.1 RADIO_E202 – 802.15.4 Channel 14

Description of Errata
Receive sensitivity of 802.15.4 channel 14 is lower than expected. The average receive sensitivity of 802.15.4 channel 14 is currently –98 dBm.
Affected Conditions / Impacts
The average receive sensitivity of 802.15.4 channel 14 is currently lower than expected.
Workaround
There is currently no workaround for this issue.
Resolution
This issue is documented in the revision 1.0 and later device data sheet.

2.2 RADIO_E203 – Bluetooth Smart Channel 26

Description of Errata
Receive sensitivity of Bluetooth Smart channel 26 (2458 MHz) is lower than expected. The average receive sensitivity of Bluetooth Smart Channel 26 is currently –86 dBm (Reference Signal) and –85 dBm (Dirty Transmitter).
Affected Conditions / Impacts
Receive sensitivity of Bluetooth Smart channel 26 is worse than expected.
Workaround
There is currently no workaround for this issue.
Resolution
This issue is documented in the revision 1.0 and later device data sheet.

2.3 RADIO_E204 – Increased EVM on Selected Channels

Description of Errata
EVM is increased for one 802.15.4 channel.
Affected Conditions / Impacts
Typical EVM will be increased to 7.8% for the 2415 MHz 802.15.4 channel.
Workaround
No workaround required. The 802.15.4 specification requires an EVM of less than 35%.
Resolution
This issue is documented in the revision 1.0 and later device data sheet.

3. Revision History

3.1 Revision 1.5

November 11, 2016

Added DCDC_E202 and DCDC_E203 to [Table 1.1 Errata History Overview on page 1](#).

3.2 Revision 1.4

July 13th, 2016

Initial revision.

Moved RADIO_E202, RADIO_E203, and RADIO_E204 from the errata to the errata history.

Silicon Labs

Simplicity Studio™4



Simplicity Studio

One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



IoT Portfolio
www.silabs.com/IoT



SW/HW
www.silabs.com/simplicity



Quality
www.silabs.com/quality



Support and Community
community.silabs.com

Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice and limitation to product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Silicon Labs shall have no liability for the consequences of use of the information supplied herein. This document does not imply or express copyright licenses granted hereunder to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any Life Support System without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons.

Trademark Information

Silicon Laboratories Inc.®, Silicon Laboratories®, Silicon Labs®, SiLabs® and the Silicon Labs logo®, Bluegiga®, Bluegiga Logo®, Clockbuilder®, CMEMS®, DSPLL®, EFM®, EFM32®, EFR®, Ember®, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Ember®, EZLink®, EZRadio®, EZRadioPRO®, Gecko®, ISOModem®, Precision32®, ProSLIC®, Simplicity Studio®, SiPHY®, Telegesis, the Telegesis Logo®, USBXpress® and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. All other products or brand names mentioned herein are trademarks of their respective holders.



SILICON LABS

Silicon Laboratories Inc.
400 West Cesar Chavez
Austin, TX 78701
USA

<http://www.silabs.com>