



Wireless Gecko EFR32MG22 Errata



This document contains information on the EFR32MG22 errata. The latest available revision of this device is revision C.

Errata that have been resolved remain documented and can be referenced for previous revisions of this device.

The device data sheet explains how to identify the chip revision, either from the package marking or electronically.

Errata effective date: December, 2022.

1. Errata Summary

The table below lists all known errata for the EFR32MG22 and all unresolved errata of the EFR32MG22.

Table 1.1. Errata Overview

Designator	Title/Problem	Workaround Exists	Exists on Revision:	
			B	C
CMU_E301	Hard Fault Exiting EM2 or EM3 with Debugger Attached	Yes	X	—
CMU_E302	LFRCO Precision Mode Is Not Functional	No	X	—
CMU_E303	Outputting the HFXO or HFRCO to a Pin Can Hang the Device in EM2/EM3	Yes	X	—
CUR_E302	Extra EM1 Current if FPU is Disabled	Yes	X	X
DCDC_E302	DCDC Interrupts Block EM2/3 Entry or Cause Unexpected Wake-up	Yes	X	X
EMU_E301	Request for Averaged Temperature Reading Can Be Missed	Yes	X	—
EMU_E302	DC-DC is Disabled after a Soft Reset	Yes	X	—
EMU_E303	Watchdog Reset Hangs System Entering EM2 or EM3	Yes	X	X
EUART_E301	EUART Receiver Enters Lockup State when Using Low Frequency IrDA Mode	Yes	X	X
EUART_E302	Incorrect Stop Bits Lock Receiver	Yes	X	X
I2C_E303	I2C Fails to Indicate New Incoming Data	Yes	X	X
IADC_E306	Changing Gain During a Scan Sequence Causes an Erroneous IADC Result	Yes	X	X
RADIO_E302	Data Whitening is not Selective	No	X	X
RADIO_E303	RAIL Packet Filters Work Incorrectly When Header is Enabled	Yes	X	X
TIMER_E301	Continuous Overflow and Underflow Interrupts in Quadrature Counting Mode	Yes	X	X
USART_E301	Possible Data Transmission on Wrong Edge in Synchronous Mode	Yes	X	X
USART_E302	Additional SCLK Pulses Can Be Generated in USART Synchronous Mode	Yes	X	X
USART_E304	PRS Transmit Unavailable in Synchronous Secondary Mode	No	X	X
WDOG_E301	Clear Command is Lost Upon EM2 Entry	Yes	X	—

2. Current Errata Descriptions

2.1 CUR_E302 – Extra EM1 Current if FPU is Disabled

Description of Errata
When the Floating Point Unit (FPU) is disabled, the on-demand Fast Startup RC Oscillator (FSRCO) remains on after an energy mode transition from EM0 to EM1 is complete. This leads to higher current consumption in EM1.
Affected Conditions / Impacts
The enabled FSRCO increases EM1 current consumption by approximately 500 µA.
Workaround
Always enable the FPU at the beginning of code execution via the Coprocessor Access Control Register (CPACR) in the System Control Block (SCB) as shown below:
<pre>SCB->CPACR = ((3 << 20) (3 << 22));</pre>
Resolution
There is currently no resolution for this issue.

2.2 DCDC_E302 – DCDC Interrupts Block EM2/3 Entry or Cause Unexpected Wake-up

Description of Errata
Regardless of the setting of the DCDC Interrupt Enable (DCDC_IEN) register, if the DCDC interrupt is enabled in the NVIC, the BYPSW, WARM, RUNNING, or TMAX interrupt requests can wake the device from EM2/3 or prevent it from entering EM2/3.
Affected Conditions / Impacts
The errata is limited to the BYPSW, WARM, RUNNING, or TMAX requests as reflected in the DCDC Interrupt Flag (DCDC_IF) register, which also function as wake-up sources from EM2/3.
When the NVIC DCDC interrupt is enabled: <ul style="list-style-type: none"> • If the corresponding DCDC_IEN bit for one of these interrupt requests is 1 and that condition occurs, then an interrupt will occur, and the CPU will branch to the DCDC IRQ handler. • If the corresponding DCDC_IEN bit for one of these interrupt requests is 0 and that condition occurs, then an interrupt will not occur. • If any one of these four interrupt conditions occurs, regardless of the setting of its corresponding DCDC_IEN bit, the device will wake from EM2/3 and/or be prevented from entering EM2/3. If the corresponding IEN is 0, an interrupt will not occur even though the EM2/3 wakeup event has occurred.
Workaround
To prevent unwanted wake-up from or blocked entry into EM2/3, disable the DCDC interrupt using <code>NVIC_DisableIRQ(DCDC_IRQn)</code> before entering EM2/3 and re-enable the DCDC interrupt using <code>NVIC_EnableIRQ(DCDC_IRQn)</code> after EM2/3 wake-up.
Resolution
There is currently no resolution for this issue.

2.3 EMU_E303 – Watchdog Reset Hangs System Entering EM2 or EM3

Description of Errata
<p>The chip can hang and require a hard reset (pin or power-on) to recover if:</p> <ol style="list-style-type: none">1. The system is operating with VSCALE1 core voltage scaling (software has previously written a 1 to the EMU_CMD_EM01VSCALE1 bit),2. The system is in the process of entering EM2 or EM3 (software has just executed the WFE or WFI instruction with the SLEEP-DEEP bit in the System Control Register set), and3. A Watchdog timeout reset is triggered.
Affected Conditions / Impacts
<p>Systems operating with core voltage scaling can hang if a Watchdog reset occurs immediately upon EM2 or EM3 entry.</p>
Workaround
<p>Systems that keep the Watchdog enabled in low energy modes should, as a matter of good programming practice, service the Watchdog before entering EM2 or EM3. Calling the <code>emlib WDOGn_Feed()</code> function followed by the <code>WDOGn_SyncWait()</code> function (to ensure that the servicing write to the WDOG_CMD register completes execution) immediately before entering EM2 or EM3 will prevent a Watchdog reset that could possibly hang the system under the specified circumstances.</p>
Resolution
<p>There is currently no resolution for this issue.</p>

2.4 EUART_E301 — EUART Receiver Enters Lockup State when Using Low Frequency IrDA Mode

Description of Errata
<p>When low frequency IrDA mode is enabled (EUSART_IRLFCFG_IRLFEN = 1), the receiver can block incoming traffic if it receives either a...</p> <ul style="list-style-type: none">• 0 if EUSART_CFG0_RXINV = 0 or• 1 if EUSART_CFG0_RXINV = 1 <p>...before...</p> <ul style="list-style-type: none">• the EUART module is enabled (EUSART_EN_EN = 1),• the receiver is enabled (EUSART_CMD_RXEN = 1), and• the write to enable the receiver (RXEN = 1) has been synchronized (EUSART_SYNCBUSY_RXEN = 0).
Affected Conditions / Impacts
<p>Incoming traffic will be blocked at the EUART receiver and subsequent interrupts and status flags will not be set correctly.</p>
Workaround

To avoid entering the lockup state, use one of the workarounds mentioned below:

- When the receiver (RX) input is routed through the PRS:

Force the input to the IrDA demodulator to high by using the PRS before enabling EUART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Output logic 0 through PRS Channel that is connected to EUART RX GPIO
PRS->ASYNC_CH[0].CTRL = PRS_ASYNC_CH_CTRL_FNSEL_LOGICAL_ZERO |
                        PRS_ASYNC_CH_CTRL_SOURCESEL_GPIO | PRS_ASYNC_CH_CTRL_SIGSEL_GPIOPIN0;

// Select PRS as input to Rx
EUART0->CFG1_SET = EUSART_CFG1_RXPRSEN;

// Enable EUART to configure Rx
EUART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Output EUART RX through PRS Channel
PRS->ASYNC_CH[0].CTRL = (PRS->ASYNC_CH[0].CTRL & ~PRS_ASYNC_CH_CTRL_FNSEL_MASK) |
                        PRS_ASYNC_CH_CTRL_FNSEL_A;
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

- When the receiver (RX) input is not routed through the PRS:

Force the input to the IrDA demodulator to high by using a GPIO pin other than the current EUART RX pin before enabling the EUART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Configure alternate GPIO (PA00) used for workaround to output 0
GPIO_PinModeSet(gpioPortA, 0, gpioModePushPull, 0);

// Route EUART0 Rx to the alternate GPIO (PA00)
GPIO->EUARTROUTE[0].RXROUTE = (gpioPortA << _GPIO_EUART_RXROUTE_PORT_SHIFT) | (0 <<
_GPIO_EUART_RXROUTE_PIN_SHIFT);

// Enable EUART0 to configure Rx
EUART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Route EUART Rx to EUART_RX GPIO(EUSRT_RX_PORT & EUART_RX_PIN)
GPIO->EUARTROUTE[0].RXROUTE = (EUART_RX_PORT << _GPIO_EUART_RXROUTE_PORT_SHIFT) | (EUART_RX_PIN <<
_GPIO_EUART_RXROUTE_PIN_SHIFT);

// Disable alternate GPIO (PA00) used for workaround
GPIO_PinModeSet(gpioPortA, 0, gpioModeDisabled, 0);
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

To exit the lockup state, disable the EUART and force the input to the IrDA demodulator to 1 before re-enabling the EUART by using steps mentioned above.

Resolution

There is currently no resolution for this issue.

2.5 EUART_E302 — Incorrect Stop Bits Lock Receiver

Description of Errata

When low frequency IrDA mode is enabled (EUSART_IRLFCFG_IRLFEN = 1), the receiver can block incoming traffic if it receives either a...

- 0 if EUSART_CFG0_RXINV = 0 or
- 1 if EUSART_CFG0_RXINV = 1

...when it is expecting a stop bit.

Affected Conditions / Impacts

Incoming traffic will be blocked at the EUART receiver. Subsequent interrupts and status flags will not be set correctly.

Workaround

To avoid receiver lock-up in the application firmware caused by formatting errors in the received data, change the receiver GPIO pin routing to force the input to the IrDA demodulator to 1 for the anticipated period of time during which such data can be received.

To exit the lockup state, disable the EUART and force the input to the IrDA demodulator to 1 before re-enabling the EUART by using one of the workarounds mentioned below:

- When the receiver (RX) input is routed through the PRS:

Force the input to the IrDA demodulator to high by using the PRS before enabling EUART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Output logic 0 through PRS Channel that is connected to EUART RX GPIO
PRS->ASYNC_CH[0].CTRL = PRS_ASYNC_CH_CTRL_FNSSEL_LOGICAL_ZERO |
                        PRS_ASYNC_CH_CTRL_SOURCESEL_GPIO | PRS_ASYNC_CH_CTRL_SIGSEL_GPIOPIN0;

// Select PRS as input to Rx
EUART0->CFG1_SET = EUSART_CFG1_RXPRSEN;

// Enable EUART to configure Rx
EUART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Output EUART RX through PRS Channel
PRS->ASYNC_CH[0].CTRL = (PRS->ASYNC_CH[0].CTRL & ~PRS_ASYNC_CH_CTRL_FNSSEL_MASK) |
                        PRS_ASYNC_CH_CTRL_FNSSEL_A;
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

- When the receiver (RX) input is not routed through the PRS:

Force the input to the IrDA demodulator to high by using a GPIO pin other than the current EUART RX pin before enabling the EUART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Configure alternate GPIO (PA00) used for workaround to output 0
GPIO_PinModeSet(gpioPortA, 0, gpioModePushPull, 0);

// Route EUART0 Rx to the alternate GPIO (PA00)
GPIO->EUARTROUTE[0].RXROUTE = (gpioPortA << _GPIO_EUART_RXROUTE_PORT_SHIFT) | (0 <<
_GPIO_EUART_RXROUTE_PIN_SHIFT);

// Enable EUART0 to configure Rx
EUART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Route EUART Rx to EUART_RX GPIO(EUSRT_RX_PORT & EUART_RX_PIN)
GPIO->EUARTROUTE[0].RXROUTE = (EUART_RX_PORT << _GPIO_EUART_RXROUTE_PORT_SHIFT) | (EUART_RX_PIN <<
_GPIO_EUART_RXROUTE_PIN_SHIFT);

// Disable alternate GPIO (PA00) used for workaround
GPIO_PinModeSet(gpioPortA, 0, gpioModeDisabled, 0);
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

Resolution

There is currently no resolution for this issue.

2.6 I2C_E303 – I²C Fails to Indicate New Incoming Data

Description of Errata
A race condition exists in which the I ² C fails to indicate reception of new data when both user software attempts to read data from and the I ² C hardware attempts to write data to the I2C_RXFIFO in the same cycle.
Affected Conditions / Impacts
When this race condition occurs, the RXFIFO enters an invalid state in which both I2C_STATUS_RXDATAV = 0 and I2C_STATUS_RXFULL = 1. This causes the I ² C to discard new incoming data bytes because RXFULL = 1 and would otherwise prevent user software from reading last byte written by the I ² C hardware to RXFIFO because RXDATAV = 0.
Workaround
User software can recognize and clear this invalid RXDATAV = 0 and RXFULL = 1 condition by performing a dummy read of the RXFIFO (I2C_RXDATA). This restores the expected RXDATAV = 1 and RXFULL = 0 condition. The dummy read also sets the RXUFIF flag bit, which should be ignored and cleared. The data from this read can be discarded, and user software can now read the last byte written by the I ² C hardware to the RXFIFO (the byte which caused the invalid RXDATAV = 0 and RXFULL = 1 condition).
No data will be lost as long as user software completes this recovery procedure (performing the dummy read and then reading the remaining valid byte in the RXFIFO) before the I ² C hardware receives the next incoming data byte.
Resolution
There is currently no resolution for this issue.

2.7 IADC_E306 – Changing Gain During a Scan Sequence Causes an Erroneous IADC Result

Description of Errata
Differences in the ANALOGGAIN setting within multiple IADC_CFGx groups during a scan sequence introduces a transient condition that may result in an inaccurate IADC conversion.
Affected Conditions / Impacts
The result of the IADC scan measurement may not match the expected result for the voltage present on the pin during the conversion.
Workaround
Both 1 and 2 shown below must be implemented. <ol style="list-style-type: none"> 1. If there is a difference in the ANALOGGAIN setting between IADC_CFGx groups during a scan sequence, the IADC_SCHEx clock prescaler must also change to an appropriate setting. This forces a warmup state (5 μs delay) in between ANALOGGAIN changes. Note that the same IADC_SCHEx clock prescaler value may be an appropriate setting for both ANALOGGAIN settings, but to force the warmup delay, the IADC_SCHEx must have different values. 2. The first and last entry of a scan group should use IADC_CFG0, which is the default configuration of the IADC at the start and end of a scan conversion sequence. If CONFIG1 is used at the start and end of the scan group, erroneous IADC results may occur.
Resolution
There is currently no resolution for this issue.

2.8 RADIO_E302 – Data Whitening is not Selective

Description of Errata
Data whitening is not selective. Enabling whitening for only the packet header also whitens the payload, while enabling whitening for only the payload also whitens the packet header.
Affected Conditions / Impacts
Radio PHYs that require selective whitening of either only the packet header or the payload will not function correctly.
Workaround
There is currently no workaround for this issue.
Resolution
There is currently no resolution for this issue.

2.9 RADIO_E303 – RAIL Packet Filters Work Incorrectly When Header is Enabled

Description of Errata
When header is enabled in the radio configurator, RAIL's address filter and 15.4 packet type filter work incorrectly
Affected Conditions / Impacts
Packets that should have been filtered will be received.
Workaround
<p>Simplicity Studio v4.1.13.6 or later and RAIL v2.8.4 in Flex SDK v2.7.4 mitigate this issue by using a workaround. The workaround is effective if:</p> <ul style="list-style-type: none">• Header and payload have the same CRC & whitening configuration.• Header and payload have the same whitening configuration, different CRC configuration and the header is less than 4 bytes long. <p>When an incompatible radio configuration setting is used, such as a 4-byte or longer header length with CRC disabled, RAIL generates a RAIL_ASSERT_INVALID_FILTERING_CONFIG error upon enabling filtering.</p>
Resolution
There is currently no resolution for this issue.

2.10 TIMER_E301 — Continuous Overflow and Underflow Interrupts in Quadrature Counting Mode

Description of Errata
When the TIMER is configured to operate in quadrature decoder mode with the overflow interrupt enabled and the counter value (TIMER_CNT) reaches the top value (TIMER_TOP), the overflow interrupt is requested continuously even if the interrupt flag (TIMER_IF_OF) is cleared. Similarly, if the underflow interrupt is enabled and the counter value reaches zero, the underflow interrupt is requested continuously even if the interrupt flag (TIMER_IF_UF) is cleared. Only after the counter value has incremented or decremented so that the overflow or underflow condition no longer applies can the interrupt be cleared.
Affected Conditions / Impacts
Because the counter is clocked by its CC0 and CC1 inputs in quadrature decoder mode and not the prescaled HPERCLK, overflow and underflow events remain latched as long TIMER_CNT remains at the value that triggered the overflow or underflow condition. Until the counter is no longer in the overflow or underflow condition, it is not possible to clear the associated interrupt flag.
Workaround
Short of disabling the relevant interrupts, the simplest workaround is to manually increment or decrement TIMER_CNT so that the overflow or underflow condition no longer exists. Insert the following or similar code in the interrupt handler for the timer in question (TIMER0 in this case) to do this:
<pre>uint32 intFlags = TIMER_IntGet(TIMER0); if (intFlags & TIMER_IEN_OF) TIMER0->CNT += 1; if (intFlags & TIMER_IEN_UF) TIMER0->CNT -= 1;</pre>
It may be necessary for firmware to account for this adjustment in calculations that include the counter value.
Resolution
There is currently no resolution for this issue.

2.11 USART_E301 — Possible Data Transmission on Wrong Edge in Synchronous Mode

Description of Errata
<p>The first bit of the new data word is incorrectly transmitted on the leading clock edge of the subsequent data bit and not the trailing clock edge of the current data bit if the USART is configured to operate in synchronous mode with</p> <ol style="list-style-type: none"> 1. USART_CLKDIV_DIV = 0 (clock = $f_{HFPERCLK} \div 2$), 2. USART_CTRL_CLKPHA = 0, 3. USART_TIMING_CSHOLD = 1 and 4. Data is loaded into the transmit FIFO (say, by the LDMA) at the exact same time as the USART state machine begins to insert the requested one bit time extension of the chip select hold time (USART_TIMING_CSHOLD = 1).
Affected Conditions / Impacts
<p>Reception of each data bit by the secondary is tied to a specific clock edge. Therefore, the late transmission by the main of the first bit of a word may cause the secondary to receive the incorrect data, especially if the data setup time for the secondary approaches or exceeds one half the shift clock period.</p>
Workaround
<p>Because there is no way to specifically time a write to the transmit FIFO such that it does not occur when the USART state machine changes state, use one of the following workarounds to avoid the risk for data corruption described above:</p> <ul style="list-style-type: none"> • Set USART_CLK_DIV > 0. • Use USART_TIMING_CSHOLD = 0 or USART_TIMING_CSHOLD > 1. • Use USART_CTRL_CLKPHA = 1. This option is particularly useful with SPI flash memories as many support operation in both the CLKPOL = CLKPHA = 0 and CLKPOL = CLKPHA = 1 modes.
Resolution
<p>There is currently no resolution for this issue.</p>

2.12 USART_E302 — Additional SCLK Pulses Can Be Generated in USART Synchronous Mode

Description of Errata
<p>When inter-character spacing is enabled (USART_TIMING_ICS > 0) and USART_CTRL_CLKPHA = 1 in synchronous main mode, an extra clock pulse is generated after each frame transmitted except the last (that frame which when sent results in both the transmit FIFO and transmit shift register being empty).</p>
Affected Conditions / Impacts
<p>The extra clock pulse generated at the end of the first frame would cause a secondary device to clock in the first bit of the next frame it expects to receive even though the USART is not yet driving that data. The secondary would lose synchronization with the main and erroneously receive all frames after the first.</p>
Workaround
<p>Do not enable inter-character spacing when CLKPHA = 1. If a delay between frames is necessary, insert one manually with a software delay loop. Data cannot be transmitted using DMA in this case.</p>
Resolution
<p>There is currently no resolution for this issue.</p>

2.13 USART_E304 — PRS Transmit Unavailable in Synchronous Secondary Mode

Description of Errata
When the USART is configured for synchronous secondary operation, the transmit output (MISO) is not driven if the signal is routed to a pin using the PRS producer (e.g., SOURCESEL = 0x20 and SIGSEL = 0x4 for USART0).
Affected Conditions / Impacts
Systems cannot operate the USART in synchronous secondary mode if the PRS is used to route the transmit output to the RX (MISO) pin. Operation is not affected in main mode when the transmit output is routed to the TX (MOSI) pin using the PRS producer nor is operation affected in any mode when the GPIO_USARTn_RXROUTE and GPIO_USARTn_TXROUTE registers are used.
Workaround
There is currently no workaround for this issue.
Resolution
There is currently no resolution for this issue.

3. Resolved Errata Descriptions

This section contains previous errata for EFR32MG22 devices.

For errata on the latest revision, refer to the beginning of this document. The device data sheet explains how to identify chip revision, either from package marking or electronically.

3.1 CMU_E301 – Hard Fault Exiting EM2 or EM3 with Debugger Attached

Description of Errata
When waking from EM2 or EM3 with a debugger attached, the CPU clock starts approximately 40 cycles in advance of the ICACHE clock. Because the CPU resumes execution before the ICACHE is ready, the data returned in response to instruction fetches is corrupted, resulting in a hard fault exception.
Affected Conditions / Impacts
Executing code that resides in flash and wakes from EM2 or EM3 while a debugger is connected causes the system to take a hard fault exception.
Workaround
Depending on the functionality required, the hard fault condition can be avoided by: <ul style="list-style-type: none"> Detach the debugger before entering EM2 or EM3. When the debugger is attached, certain high frequency clocks remain active in EM2 or EM3, which is why the ICACHE clock is delayed relative to the CPU clock upon wake-up. Without the debugger connected, these clocks shutdown when entering EM2 or EM3 and restart together upon wake-up, thus avoiding the data corruption described above. Reconnect the debugger once the system is back in EM0 or EM1. Execute the WFI or WFE instruction that places the system in EM2 or EM3 from RAM. Upon wake-up, use a software delay loop to stall for the approximately 40 clock cycles of headstart that the CPU has before the ICACHE restarts. As above, execute WFI or WFE from RAM, but, instead of using a software delay, wait for the ICACHE_STATUS_PCRUNNING bit to change state from 0 to 1. The ICACHE performance counter must first be started by writing a 1 to ICACHE_CMD_STARTPC, which can be done either when running from flash before entering EM2 or EM3 or when running from RAM after wake-up. Stop the performance counter by writing a 1 to ICACHE_CMD_STOPPC.
Resolution
This issue is resolved in revision C devices.

3.2 CMU_E302 – LFRCO Precision Mode Is Not Functional

Description of Errata
The precision mode of the LFRCO is not functional.
Affected Conditions / Impacts
It is not possible to use the LFRCO in precision mode as a replacement for a 32.768 kHz crystal.
Workaround
There is currently no workaround for this issue. Use the LFXO and a suitable 32.768 kHz crystal in applications with such requirements.
Resolution
This issue is resolved in revision C devices.

3.3 CMU_E303 — Outputting the HFXO or HFRCO to a Pin Can Hang the Device in EM2/EM3

Description of Errata
The device hangs when attempting to enter EM2 or EM3 while the HFXO or HFRCO is driven on one of the CLKOUT pins without a debugger connected.
Affected Conditions / Impacts
It is not possible to enter EM2 or EM3 when the HFXO or HFRCO is driven on one of the CLKOUT pins nor will an interrupt wake the device that has hung in this way.
Workaround
Deselect the HFXO or HFRCO on any CLKOUT pins before entering EM2 or EM3. For example, to de-select the HFXO or HFRCO on pin PC03, add the following function call before entering EM2 or EM3:
<pre>CMU_ClkOutPinConfig(0, cmuSelect_Disabled, 0, gpioPortC, 3);</pre>
Resolution
This issue is resolved in revision C devices.

3.4 EMU_E301 – Request for Averaged Temperature Reading Can Be Missed

Description of Errata
Depending on the system clock frequency, the request for a hardware-averaged temperature reading is sometimes not captured, and the state machine that generates the averaged reading is never started.
Affected Conditions / Impacts
Because the averaging state machine is never started, the EMU_IF_TEMPVIF flag is never set, and any code that depends on the averaged reading is not going to execute.
Workaround
Subsequent EMU register accesses will cause the temperature averaging request to be recognized, so the simplest solution to ensure this is to use the following code sequence:
<pre>EMU->CMD_SET = EMU_CMD_TEMPVIFREQ; while (!(EMU->STATUS & EMU_STATUS_TEMPVIFACTIVE));</pre>
Resolution
This issue is resolved in revision C devices.

3.5 EMU_E302 – DC-DC is Disabled after a Soft Reset

Description of Errata
The DC-DC converter stops regulating after a soft reset until it is re-enabled.
Affected Conditions / Impacts
When disabled, the DC-DC operates in bypass mode. Supplies connected to the DC-DC output will be powered at the VREGIN voltage which increases current consumption, until the DC-DC is re-enabled.
Workaround
On devices prior to revision C, firmware must re-enable the DC-DC after a soft reset.
Resolution
This issue has been resolved. Revision C devices with PRODREV greater than or equal to 1 will not have this issue.

3.6 WDOG_E301 – Clear Command is Lost Upon EM2 Entry

Description of Errata
If the device enters EM2, while the clear command is still being synchronized, the watchdog counter may not be cleared as expected.
Affected Conditions / Impacts
If the watchdog counter is not cleared as expected, the device can encounter a watchdog reset.
Workaround
Wait for WDOG_SYNCBUSY_CMD to clear before entering EM2. Note that WDOG can be clocked from one of the low-frequency clock sources and will require additional time to enter EM2 when implementing this workaround.
Resolution
This issue is resolved in revision C devices.

4. Revision History

Revision 0.7

December, 2022

- Added [DCDC_E302](#), [EUART_E301](#), [EUART_E302](#) and [IADC_E306](#).

Revision 0.6

July, 2021

- Added [USART_E304](#).
- Updated the workaround in [I2C_E303](#).
- Added [CUR_E302](#).
- Replaced select terms with inclusive lexicon.

Revision 0.5

September, 2020

- Added [I2C_E303](#).
- Clarified the affected conditions and impacts in [WDOG_E301](#).
- Updated affected revisions and resolution for [TIMER_E301](#).

Revision 0.4

May, 2020

- Added [RADIO_E303](#) and [USART_E302](#).

Revision 0.3

January, 2020

- Added [EMU_E303](#) and [RADIO_E302](#).

Revision 0.2

October, 2019

- Updated to product revision C.
- Added [CMU_E303](#), [EMU_E302](#), [TIMER_E301](#) and [WDOG_E301](#).
- Resolved [CMU_E301](#), [CMU_E302](#) and [EMU_E301](#)
- Migrated to new errata document format.

Revision 0.1

July, 2019

- Initial release.

Simplicity Studio

One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



IoT Portfolio
www.silabs.com/IoT



SW/HW
www.silabs.com/simplicity



Quality
www.silabs.com/quality



Support & Community
www.silabs.com/community

Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

Note: This content may contain offensive terminology that is now obsolete. Silicon Labs is replacing these terms with inclusive language wherever possible. For more information, visit www.silabs.com/about-us/inclusive-lexicon-project

Trademark Information

Silicon Laboratories Inc.[®], Silicon Laboratories[®], Silicon Labs[®], SiLabs[®] and the Silicon Labs logo[®], Bluegiga[®], Bluegiga Logo[®], EFM[®], EFM32[®], EFR, Ember[®], Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals[®], WiSeConnect, n-Link, ThreadArch[®], EZLink[®], EZRadio[®], EZRadioPRO[®], Gecko[®], Gecko OS, Gecko OS Studio, Precision32[®], Simplicity Studio[®], Telegesis, the Telegesis Logo[®], USBXpress[®], Zentri, the Zentri logo and Zentri DMS, Z-Wave[®], and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.
400 West Cesar Chavez
Austin, TX 78701
USA

www.silabs.com