



Z-Wave 800 SiP Module ZGM230S Errata



This document contains information on the ZGM230S errata. The latest available revision of this device is revision 3.

Errata that have been resolved remain documented and can be referenced for previous revisions of this device.

Errata effective date: February, 2023.

1. Errata Summary

The table below lists all known errata for the ZGM230S and all unresolved errata of the ZGM230S.

Table 1.1. Errata Overview

Designator	Title/Problem	Workaround Exists	Exists on Revision:	
			2	3
CUR_E302	Extra EM1 Current if FPU is Disabled	Yes	X	X
CUR_E303	Active Charge Pump Clock Causes High Current	Yes	X	—
DCDC_E302	DCDC Interrupts Block EM2/3 Entry or Cause Unexpected Wake-up	Yes	X	X
EMU_E305	DC-DC Refresh Time Delay	Yes	X	X
EUSART_E303	EUSART Receiver Enters Lockup State when Using Low Frequency IrDA Mode	Yes	X	X
EUSART_E304	Incorrect Stop Bits Lock Receiver	Yes	X	X
IADC_E305	FIFO Cannot Detect Eighth Entry	Yes	X	X
IADC_E306	Changing Gain During a Scan Sequence Causes an Erroneous IADC Result	Yes	X	X
KEYSCAN_E301	Unused Rows Are Not Properly Gated Off	Yes	X	X
LCD_E301	LOADBUSY Status Goes Inactive Early With Prescaled Clock	Yes	X	X
USART_E304	PRS Transmit Unavailable in Synchronous Secondary Mode	No	X	X

2. Current Errata Descriptions

There are no known errata for revision C of this device.

2.1 CUR_E302 – Extra EM1 Current if FPU is Disabled

Description of Errata
When the Floating Point Unit (FPU) is disabled, the on-demand Fast Startup RC Oscillator (FSRCO) remains on after an energy mode transition from EM0 to EM1 is complete. This leads to higher current consumption in EM1.
Affected Conditions / Impacts
The enabled FSRCO increases EM1 current consumption by approximately 500 µA.
Workaround
Always enable the FPU at the beginning of code execution via the Coprocessor Access Control Register (CPACR) in the System Control Block (SCB) as shown below:
<pre>SCB->CPACR = ((3 << 20) (3 << 22));</pre>
Resolution
There is currently no resolution for this issue.

2.2 DCDC_E302 – DCDC Interrupts Block EM2/3 Entry or Cause Unexpected Wake-up

Description of Errata
Regardless of the setting of the DCDC Interrupt Enable (DCDC_IEN) register, if the DCDC interrupt is enabled in the NVIC, the BYPSW, WARM, RUNNING, or TMAX interrupt requests can wake the device from EM2/3 or prevent it from entering EM2/3.
Affected Conditions / Impacts
The errata is limited to the BYPSW, WARM, RUNNING, or TMAX requests as reflected in the DCDC Interrupt Flag (DCDC_IF) register, which also function as wake-up sources from EM2/3.
When the NVIC DCDC interrupt is enabled:
<ul style="list-style-type: none"> • If the corresponding DCDC_IEN bit for one of these interrupt requests is 1 and that condition occurs, then an interrupt will occur, and the CPU will branch to the DCDC IRQ handler. • If the corresponding DCDC_IEN bit for one of these interrupt requests is 0 and that condition occurs, then an interrupt will not occur. • If any one of these four interrupt conditions occurs, regardless of the setting of its corresponding DCDC_IEN bit, the device will wake from EM2/3 and/or be prevented from entering EM2/3. If the corresponding IEN is 0, an interrupt will not occur even though the EM2/3 wakeup event has occurred.
Workaround
To prevent unwanted wake-up from or blocked entry into EM2/3, disable the DCDC interrupt using <code>NVIC_DisableIRQ(DCDC_IRQn)</code> before entering EM2/3 and re-enable the DCDC interrupt using <code>NVIC_EnableIRQ(DCDC_IRQn)</code> after EM2/3 wake-up.
Resolution
There is currently no resolution for this issue.

2.3 EMU_E305 – DC-DC Refresh Time Delay

Description of Errata
The DC-DC fast refresh delay required after exiting EM2/3 and entering continuous conduction mode (CCM) is not honored.
Affected Conditions / Impacts
When the system exits EM2/3 and the DC-DC is set to CCM, the DC-DC voltage comparator needs to be refreshed. This refresh delay is not honored when exiting EM2/3.
Workaround
Firmware must wait for at least 20 μ s before enabling DC-DC CCM upon wake from EM2/3.
Resolution
There is currently no resolution for this issue.

2.4 EUSART_E303 — EUSART Receiver Enters Lockup State when Using Low Frequency IrDA Mode

Description of Errata
<p>When low frequency IrDA mode is enabled (EUSART_IRLFCFG_IRLFEN = 1), the receiver can block incoming traffic if it receives either a...</p> <ul style="list-style-type: none">• 0 if EUSART_CFG0_RXINV = 0 or• 1 if EUSART_CFG0_RXINV = 1 <p>...before...</p> <ul style="list-style-type: none">• the EUSART module is enabled (EUSART_EN_EN =1),• the receiver is enabled (EUSART_CMD_RXEN =1), and• the write to enable the receiver (RXEN = 1) has been synchronized (EUSART_SYNCBUSY_RXEN = 0).
Affected Conditions / Impacts
Incoming traffic will be blocked at the EUSART receiver and subsequent interrupts and status flags will not be set correctly.
Workaround

To avoid entering the lockup state, use one of the workarounds mentioned below:

- When the receiver (RX) input is routed through the PRS:

Force the input to the IrDA demodulator to high by using the PRS before enabling EUSART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Output logic 0 through PRS Channel that is connected to EUSART RX GPIO
PRS->ASYNC_CH[0].CTRL = PRS_ASYNC_CH_CTRL_FNSEL_LOGICAL_ZERO |
    PRS_ASYNC_CH_CTRL_SOURCESEL_GPIO | PRS_ASYNC_CH_CTRL_SIGSEL_GPIOPIN0;

// Select PRS as input to RX.
EUSART0->CFG1_SET = EUSART_CFG1_RXPRSEN;

// Enable EUSART to configure Rx
EUSART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUSART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUSART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Output EUSART RX pin through PRS Channel
PRS->ASYNC_CH[0].CTRL = (PRS->ASYNC_CH[0].CTRL & ~PRS_ASYNC_CH_CTRL_FNSEL_MASK) |
    PRS_ASYNC_CH_CTRL_FNSEL_A;
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

- When the receiver (RX) input is not routed through the PRS:

Force the input to the IrDA demodulator to high by using a GPIO pin other than the current EUSART RX pin before enabling the EUSART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Configure alternate GPIO (PA00) used for workaround to output 0
GPIO_PinModeSet(gpioPortA, 0, gpioModePushPull, 0);

// Route EUSART0 Rx to the alternate GPIO (PA00)
GPIO->EUSARTROUTE[0].ROUTEEN = (GPIO->EUSARTROUTE[0].ROUTEEN & ~GPIO_EUSART_ROUTEEN_RXPEN);
GPIO->EUSARTROUTE[0].RXROUTE = (gpioPortA << _GPIO_EUSART_RXROUTE_PORT_SHIFT) | (0 <<
    _GPIO_EUSART_RXROUTE_PIN_SHIFT);
GPIO->EUSARTROUTE[0].ROUTEEN |= GPIO_EUSART_ROUTEEN_RXPEN;

// Enable EUSART0 to configure Rx
EUSART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUSART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUSART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Route EUSART Rx to EUSART_RX GPIO(EUSART_RX_PORT & EUSART_RX_PIN)
GPIO->EUSARTROUTE[0].ROUTEEN = (GPIO->EUSARTROUTE[0].ROUTEEN & ~GPIO_EUSART_ROUTEEN_RXPEN);
GPIO->EUSARTROUTE[0].RXROUTE = (EUSART_RX_PORT << _GPIO_EUSART_RXROUTE_PORT_SHIFT) | (EUSART_RX_PORT <<
    _GPIO_EUSART_RXROUTE_PIN_SHIFT);
GPIO->EUSARTROUTE[0].ROUTEEN |= GPIO_EUSART_ROUTEEN_RXPEN;

// Disable alternate GPIO (PA00) used for workaround
GPIO_PinModeSet(gpioPortA, 0, gpioModeDisabled, 0);
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

To exit the lockup state, disable the EUART and force the input to the IrDA demodulator to 1 before re-enabling the EUART by using steps mentioned above.

Resolution

There is currently no resolution for this issue.

2.5 EUSART_E304 — Incorrect Stop Bits Lock Receiver

Description of Errata

When low frequency IrDA mode is enabled (EUSART_IRLFCFG_IRLFEN = 1), the receiver can block incoming traffic if it receives either a...

- 0 if EUSART_CFG0_RXINV = 0 or
- 1 if EUSART_CFG0_RXINV = 1

...when it is expecting a stop bit.

Affected Conditions / Impacts

Incoming traffic will be blocked at the EUSART receiver. Subsequent interrupts and status flags will not be set correctly.

Workaround

To avoid receiver lock-up in the application firmware caused by formatting errors in the received data, change the receiver GPIO pin routing to force the input to the IrDA demodulator to 1 for the anticipated period of time during which such data can be received.

To exit the lockup state, disable the EUSART and force the input to the IrDA demodulator to 1 before re-enabling the EUSART by using one of the workarounds mentioned below:

- When the receiver (RX) input is routed through the PRS:

Force the input to the IrDA demodulator to high by using the PRS before enabling EUSART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Output logic 0 through PRS Channel that is connected to EUSART RX GPIO
PRS->ASYNC_CH[0].CTRL = PRS_ASYNC_CH_CTRL_FNSSEL_LOGICAL_ZERO |
                        PRS_ASYNC_CH_CTRL_SOURCESEL_GPIO | PRS_ASYNC_CH_CTRL_SIGSEL_GPIOPIN0;

// Select PRS as input to Rx
EUSART0->CFG1_SET = EUSART_CFG1_RXPRSEN;

// Enable EUSART to configure Rx
EUSART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUSART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUSART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Output EUSART RX through PRS Channel
PRS->ASYNC_CH[0].CTRL = (PRS->ASYNC_CH[0].CTRL & ~PRS_ASYNC_CH_CTRL_FNSSEL_MASK) |
                        PRS_ASYNC_CH_CTRL_FNSSEL_A;
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

- When the receiver (RX) input is not routed through the PRS:

Force the input to the IrDA demodulator to high by using a GPIO pin other than the current EUSART RX pin before enabling the EUSART. Keep it this way until the receiver has been enabled and EUSART_CMD_RXEN bit is synchronized. See the following code sequence for an example of how to do this:

```
// Configure alternate GPIO (PA00) used for workaround to output 0
GPIO_PinModeSet(gpioPortA, 0, gpioModePushPull, 0);

// Route EUSART0 Rx to the alternate GPIO (PA00)
GPIO->EUSARTROUTE[0].RXROUTE = (gpioPortA << _GPIO_EUSART_RXROUTE_PORT_SHIFT) | (0 <<
_GPIO_EUSART_RXROUTE_PIN_SHIFT);

// Enable EUSART0 to configure Rx
EUSART0->EN_SET = EUSART_EN_EN;

// Enable Rx
EUSART0->CMD = EUSART_CMD_RXEN;

// Wait until Rx enable is synchronized
while ((EUSART0->SYNCBUSY & EUSART_SYNCBUSY_RXEN) != 0U) {}

// Route EUSART Rx to EUSART_RX GPIO(EUSRT_RX_PORT & EUSART_RX_PIN)
GPIO->EUSARTROUTE[0].RXROUTE = (EUSART_RX_PORT << _GPIO_EUSART_RXROUTE_PORT_SHIFT) | (EUSART_RX_PIN <<
_GPIO_EUSART_RXROUTE_PIN_SHIFT);

// Disable alternate GPIO (PA00) used for workaround
GPIO_PinModeSet(gpioPortA, 0, gpioModeDisabled, 0);
```

Note: EUSART_CTRL_RXINV = 1 in this workaround because the receiver input must be inverted for proper IrDA RZI operation.

Resolution

There is currently no resolution for this issue.

2.6 IADC_E305 – FIFO Cannot Detect Eighth Entry

Description of Errata
The IADC is unable to detect when the eighth FIFO entry has been loaded and will not set the corresponding SINGLEFIFODVL or SCANFIFODVL flag in the IADC_IF register or request LDMA service.
Affected Conditions / Impacts
<p>If the DVL field of IADC_SINGLEFIFOCFG or IADC_SCANFIFOCFG is set to VALID8, a FIFO full condition is not registered when the eighth FIFO entry is loaded. In particular, this means that if the LDMA is configured to empty the FIFO when it is filled with eight entries, the LDMA will never issue a request to perform the transfers necessary to do this.</p> <p>Similarly, the IADC will not set the IADC_IF_SINGLEFIFODVL or IADC_IF_SCANFIFODVL to request an interrupt in response to the FIFO being filled with eight entries.</p>
Workaround
Do not configure the IADC to request an interrupt or LDMA service when all eight entries are full (IADC_SINGLEFIFOCFG_DVL = VALID8 or IADC_SCANFIFOCFG_DVL = VALID8). All other settings of the DVL field (VALID1 to VALID7) operate as expected.
Resolution
There is currently no resolution for this issue.

2.7 IADC_E306 – Changing Gain During a Scan Sequence Causes an Erroneous IADC Result

Description of Errata
Differences in the ANALOGGAIN setting within multiple IADC_CFGx groups during a scan sequence introduces a transient condition that may result in an inaccurate IADC conversion.
Affected Conditions / Impacts
The result of the IADC scan measurement may not match the expected result for the voltage present on the pin during the conversion.
Workaround
<p>Both 1 and 2 shown below must be implemented.</p> <ol style="list-style-type: none"> 1. If there is a difference in the ANALOGGAIN setting between IADC_CFGx groups during a scan sequence, the IADC_SCHEx clock prescaler must also change to an appropriate setting. This forces a warmup state (5 μs delay) in between ANALOGGAIN changes. Note that the same IADC_SCHEx clock prescaler value may be an appropriate setting for both ANALOGGAIN settings, but to force the warmup delay, the IADC_SCHEx must have different values. 2. The first and last entry of a scan group should use IADC_CFG0, which is the default configuration of the IADC at the start and end of a scan conversion sequence. If CONFIG1 is used at the start and end of the scan group, erroneous IADC results may occur.
Resolution
There is currently no resolution for this issue.

2.8 KEYSCAN_E301 – Unused Rows Are Not Properly Gated Off

Description of Errata
Unused KEYSCAN row inputs cause the KEY bit in the KEYSCAN_IF register to be set at all times indicating a key was pressed. This prevents the interrupt flag from clearing and stops the scan procedure.
Affected Conditions / Impacts
The KEY bit in the KEYSCAN_IF register is always set when rows are left unused.
Workaround
<p>Configure the GPIO_KEYSCAN_ROWSENSEnROUTE registers for any unused row inputs to the same GPIO port and pin associated with any of the row inputs that are used. For example, if rows 0, 1, and 2 are used and routed to PA05, PA06, and PA07 respectively, and rows 3, 4, and 5 are unused, the configuration could be:</p> <pre>// Routing GPIO pins PA05, PA06 and PA07 to rows 0, 1 and 2 GPIO->DBUSKEYPAD_ROWSENSE0ROUTE = 0 << _GPIO_DBUSKEYPAD_ROWSENSE0ROUTE_PORT_SHIFT 5 << _GPIO_DBUSKEYPAD_ROWSENSE0ROUTE_PIN_SHIFT; GPIO->DBUSKEYPAD_ROWSENSE1ROUTE = 0 << _GPIO_DBUSKEYPAD_ROWSENSE1ROUTE_PORT_SHIFT 6 << _GPIO_DBUSKEYPAD_ROWSENSE1ROUTE_PIN_SHIFT; GPIO->DBUSKEYPAD_ROWSENSE2ROUTE = 0 << _GPIO_DBUSKEYPAD_ROWSENSE2ROUTE_PORT_SHIFT 7 << _GPIO_DBUSKEYPAD_ROWSENSE2ROUTE_PIN_SHIFT; // Workaround - Connect unused rows 3, 4, and 5 to row 2 (PA07), a single used row GPIO->KEYSCANROUTE_ROWSENSE3ROUTE = 0 << _GPIO_KEYSCAN_ROWSENSE3ROUTE_PORT_SHIFT 7 << _GPIO_KEYSCAN_ROWSENSE3ROUTE_PIN_SHIFT; GPIO->KEYSCANROUTE_ROWSENSE4ROUTE = 0 << _GPIO_KEYSCAN_ROWSENSE4ROUTE_PORT_SHIFT 7 << _GPIO_KEYSCAN_ROWSENSE4ROUTE_PIN_SHIFT; GPIO->KEYSCANROUTE_ROWSENSE5ROUTE = 0 << _GPIO_KEYSCAN_ROWSENSE5ROUTE_PORT_SHIFT 7 << _GPIO_KEYSCAN_ROWSENSE5ROUTE_PIN_SHIFT;</pre> <p>Note that KEYSCAN_STATUS.ROW will report the same values for used and unused rows that route to the same GPIO. In the scenario above, KEYSCAN_STATUS.ROW bits 2, 3, 4, and 5 will show the same values. The unused row bits in the KEYSCAN_STATUS field should be masked so that unused row bits are set to 1, indicating a key is not pressed.</p>
Resolution
There is currently no resolution for this issue.

2.9 LCD_E301 — LOADBUSY Status Goes Inactive Early With Prescaled Clock

Description of Errata
The LCD_STATUS_LOADBUSY bit erroneously reports completion of writes to the LCD_BCTRL, LCD_AREGA, LCD_AREGB, and LCD_SEGDn registers before synchronization is complete when LCD_CTRL_PRESCALE > 3.
Affected Conditions / Impacts
If LOADBUSY is used to gate consecutive writes to one of the affected registers, only the data associated with the last write is guaranteed to be latched into the register.
Workaround
For each write to one of the affected registers, insert a delay equal to $\text{LCD_CTRL_PRESCALE} \div f_{\text{LCDCLK}}$ after LOADBUSY transitions from 1 to 0 before issuing the next write to the same register.
Note: LOADBUSY reports when data written from the PCLK register domain into the LCD controller's low-frequency clock domain has been synchronized. It does not indicate when data written into one of the affected registers is actually driven on the LCD controller pins.
In cases where writes to these registers, such as LCD_SEGDn, are intended to have the change in pin state be observable on the connected display, LOADBUSY should not be used to gate consecutive writes. Instead, the CPU should issue the register write and wait to issue the next write until a display update event or frame counter update event occurs as reported by the LCD_IF register DISPLAY or FC flag bits. Interrupts associated with these flags can and should be enabled in such cases to minimize energy use by keeping the CPU in a low-energy mode (e.g., EM2) between such consecutive register writes.
Resolution
There is currently no resolution for this issue.

2.10 USART_E304 — PRS Transmit Unavailable in Synchronous Secondary Mode

Description of Errata
When the USART is configured for synchronous secondary operation, the transmit output (MISO) is not driven if the signal is routed to a pin using the PRS producer (e.g., SOURCESEL = 0x20 and SIGSEL = 0x4 for USART0).
Affected Conditions / Impacts
Systems cannot operate the USART in synchronous secondary mode if the PRS is used to route the transmit output to the RX (MISO) pin. Operation is not affected in main mode when the transmit output is routed to the TX (MOSI) pin using the PRS producer nor is operation affected in any mode when the GPIO_USARTn_RXROUTE and GPIO_USARTn_TXROUTE registers are used.
Workaround
There is currently no workaround for this issue.
Resolution
There is currently no resolution for this issue.

3. Resolved Errata Descriptions

This section contains previous errata for ZGM230S devices.

For errata on the latest revision, refer to the beginning of this document. The device data sheet explains how to identify chip revision, either from package marking or electronically.

3.1 CUR_E303 – Active Charge Pump Clock Causes High Current

Description of Errata
When the ACMP0, ACMP1, or IADC0 peripherals are active, the clock to the internal analog mux charge pump may also be activated, resulting in extra supply current.
Affected Conditions / Impacts
<ul style="list-style-type: none">ACMP0 and ACMP1: The charge pump clock is activated whenever either module is enabled via the ACMPn_EN_EN bit or when enabled by the LESENSE state machine.IADC0: The charge pump clock is activated when any portion of the IADC analog circuitry is on. When IADC_CTRL_WARMUPMODE = KEEPINSTANDBY or KEEPWARM, the clock is activated as long as the IADC is enabled via the IADC_EN_EN bit. When IADC_CTRL_WARMUPMODE = NORMAL, the clock is activated only during warmup and conversion and will be shut down between conversions.The extra current is from a shared block and increases supply current by an approximate total of 25 μA when any of the above conditions are true.
Workaround
No workaround exists to entirely eliminate the extra current. The impact of the current can be reduced by duty-cycling the peripheral. The average system supply current increase depends on the total percentage of time the peripheral(s) is/are active. For example, if only ACMP0 is used and enabled for 10% of the time, the average supply current increase is about 2.5 μ A.
Resolution
This issue is resolved on revision 3 devices.

4. Revision History

Revision 0.4

February, 2023

- Added [LCD_E301](#).

Revision 0.3

December, 2022

- Updated latest device revision to revision 3.
- Added [EUSART_E303](#), [EUSART_E304](#), [IADC_E306](#) and [KEYSCAN_E301](#).
- Resolved [CUR_E303](#).

Revision 0.2

January, 2022

- Added [CUR_E303](#).

Revision 0.1

December, 2021

- Initial release.

Simplicity Studio


One-click access to MCU and wireless tools, documentation, software, source code libraries & more. Available for Windows, Mac and Linux!



IoT Portfolio
www.silabs.com/IoT



SW/HW
www.silabs.com/simplicity



Quality
www.silabs.com/quality



Support & Community
www.silabs.com/community

Disclaimer

Silicon Labs intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Labs products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Labs reserves the right to make changes without further notice to the product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Without prior notification, Silicon Labs may update product firmware during the manufacturing process for security or reliability reasons. Such changes will not alter the specifications or the performance of the product. Silicon Labs shall have no liability for the consequences of use of the information supplied in this document. This document does not imply or expressly grant any license to design or fabricate any integrated circuits. The products are not designed or authorized to be used within any FDA Class III devices, applications for which FDA premarket approval is required or Life Support Systems without the specific written consent of Silicon Labs. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Labs products are not designed or authorized for military applications. Silicon Labs products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons. Silicon Labs disclaims all express and implied warranties and shall not be responsible or liable for any injuries or damages related to use of a Silicon Labs product in such unauthorized applications.

Note: This content may contain offensive terminology that is now obsolete. Silicon Labs is replacing these terms with inclusive language wherever possible. For more information, visit www.silabs.com/about-us/inclusive-lexicon-project

Trademark Information

Silicon Laboratories Inc.[®], Silicon Laboratories[®], Silicon Labs[®], SiLabs[®] and the Silicon Labs logo[®], Bluegiga[®], Bluegiga Logo[®], EFM[®], EFM32[®], EFR, Ember[®], Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Redpine Signals[®], WiSeConnect, n-Link, ThreadArch[®], EZLink[®], EZRadio[®], EZRadioPRO[®], Gecko[®], Gecko OS, Gecko OS Studio, Precision32[®], Simplicity Studio[®], Telegesis, the Telegesis Logo[®], USBXpress[®], Zentri, the Zentri logo and Zentri DMS, Z-Wave[®], and others are trademarks or registered trademarks of Silicon Labs. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. Wi-Fi is a registered trademark of the Wi-Fi Alliance. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc.
400 West Cesar Chavez
Austin, TX 78701
USA

www.silabs.com