# Bluetooth Smart Software 2.4.0 build 2328

| Software Version  | 2.4.0 build 2328   |
|-------------------|--|
| Software Status   | GA   |
| Release Date      | 9th of June, 2017  |
| Affected Products | BGM11x Bluetooth Smart Modules<br>BGM12x Bluetooth Smart Modules<br>EFR32[B M]G1<br>EFR32[B M]G12<br>EFR32[B M]G13 |

# Changes: 2.4.0 (build 2328) compared to 2.3.2 (build 2263)

### **New Features**

| Feature                    | Explanation   |
|----------------------------|---|
| EFR32[B M]G13              | Support for EFR32BG13 and EFR32MG13 product families added.                         |
| BGM11S                     | Support for BGM11S <i>Bluetooth</i> Smart Module added.                             |
| Long Range                 | Bluetooth 5 Long Range support for EFR32[B M]13 product family.                     |
| PLFRCO                     | PLFRCO support for EFR32[B M]G13 product family.                                    |
| Privacy 1.2 for peripheral | Bluetooth 4.2 Privacy 1.2 for peripheral is now supported for random addressing.    |
| Polymorphic GATT DB        | This feature can be used to dynamically show or hide GATT features.                 |
| GCC compiler support       | This SDK release contains GA level support for GCC compiler version 4.9.3.          |
| CSA#2                      | Bluetooth 5 channel selection algorithm supported.                                  |
| Bonding handling algorithm | There is a new algorithm to handle bondings in a way that flash usage is minimized. |

| Feature  | Explanation   |
|--|---|
| cmd_gatt_prepare_characteristic_v<br>alue_reliable_write() | This command can be used to add a characteristic value to the write queue of a remote GATT server and verify if the value was correctly received by the server. |
| cmd_gatt_server_set_capabilities()                         | This command can be used to set which capabilities should be enabled in the local GATT database.  |
| cmd_le_gap_set_privacy_mode()                              | This command can be used to enable or disable privacy feature on all GAP roles.   |
| cmd_system_set_bt_address()                                | This command can be used to set the Bluetooth public address.   |
| cmd_system_set_device_name()                               | This command can be used to set the device name.  |
| cmd_user_message_to_target()                               | This command can be used by an NCP host to send a message to the target application on the device. Part of a new API class called user.                         |
| evt_user_message_to_host event                             | This event can be used by the target application on the device to send a message to NCP host. Part of a new API class called user.                              |

# Notes

| Note  | Explanation  |
|---|--|
| Mobile applications                           | Silicon Labs Blue Gecko application with OTA update capability is now available for both Android and iOS devices. Downloadable via Play Store and App Store. |
| BGScript for EFR32[B M]G1                     | BGScript is no longer supported for any product families.  |
| Studio version update                         | This SDK is compliant with Simplicity Studio 4.13 or newer.  |
| Simplicity Commander                          | This SDK is compliant with Simplicity Commander 0.24.1 or newer.   |
| BGAPI HW, flash and utilities command removal | The following BGAPI commands are removed in this release:  • cmd_hardware_config_adc_reference()  • cmd_hardware_configure_gpio()  • cmd_hardware_read_adc() |

| Note                                       | Explanation  |  |
|--|--|--|
|  | <ul> <li>cmd_hardware_read_adc_channel()</li> <li>cmd_hardware_read_gpio()</li> <li>cmd_hardware_read_i2c()</li> <li>cmd_hardware_set_uart_configuration()</li> <li>cmd_hardware_stop_i2c()</li> <li>cmd_hardware_write_gpio()</li> <li>cmd_hardware_write_i2c()</li> <li>cmd_util_atoi()</li> <li>cmd_util_itoa()</li> <li>The following BGAPI events will be deprecated in the next major release:</li> <li>evt_hardware_interrupt</li> <li>The following BGAPI enumerations will be deprecated in the next major release:</li> <li>enum_hardware_adc_channel</li> <li>enum_hardware_adc_reference</li> <li>enum_hardware_gpio_mode</li> <li>enum_hardware_uartparity</li> </ul> |  |
| cmd_gatt_server_set_database()             | This command is now deprecated and will be removed in future releases.   |  |
| enum_le_connection_security                | Extended with le_connection_mode1_level4 to be used for authenticated secure connections pairing with encryption using a 128-bit strength encryption key.  |  |
| IAR libraries for building Bluetooth stack | <ul> <li>Bluetooth SDK now includes the following libraries for IAR projects:</li> <li>bgapi.a</li> <li>libbluetooth.a</li> <li>libembedtls.a</li> <li>librail.a</li> <li>libbootloader_api.a</li> <li>Note that in-place OTA DFU will not work when the stack is built using these libraries.</li> </ul>  |  |

## **Quality Improvements**

API documentation improved
General documentation updates
Example applications and demos updated in the SDK
Improvements and bugs fixes in Visual GATT Editor
Continuously modulated RF signal support added

Memory handling robustness improvements for GATT operations

HW initialization simplified

PTI decoders improved for Bluetooth usage

OTA DFU throughput improvements

BGAPI command handling optimized and made faster

BGTool and bgbuild tools updated

Increased encrypted PDU size for over the air packets to 160 bytes

Gecko Bootloader version is now reported in evt\_system\_boot event (when legacy bootloaders are used, version is reported as 0)

Improvements in Switched Multi-Protocol use cases, demos and examples

BTDS plug-ins updated

BGAPI command parsing robustness improved

iOS and Android interoperability improved

Bonding handling robustness improvements

LLCP operations handling improved

#### **Fixed Known Issues since the previous Release**

| ID   | Issue                 | Explanation   |
|------|-----------------------|---|
| 1248 | Prepare write request | Prepare write request does not fail with gatt_prodecure_completed event if data is corrupted. |

| ID   | Issue                            | Explanation   |
|------|----------------------------------|---|
| 112  | le_gap_scan_response             | Event le_gap_scan_response does not contain advertising channel information.  |
| 194  | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event. |
| 247  | Connection update                | Connection update can fail if connection event is missed.   |
| 679  | HW Configurator                  | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.          |
| 1487 | Bonding with 8 slaves            | 8th consecutive bonding by master device fails with multiple slaves.  |

| ID   | Issue                          | Explanation  |
|------|--------------------------------|--|
| 1814 | IAR and GCC compiler           | One should not have both IAR and GCC toolchains active in Simplicity Studio when a new project is created. Otherwise the toolchain is automatically set to IAR, even if GCC was originally chosen. |
| 1835 | GCC breakpoints                | With certain events, GCC breakpoints cannot be set.  |
| 1992 | BTDS plug-ins                  | BTDS plug-ins do not handle multiple instances of the same service.  |
| 2220 | DTM parameters                 | DTM tests are not run correctly if invalid parameters (like unsupported PHY) are given to test commands.   |
| 2350 | Long Range connection interval | Coded PHY minimum connection interval is currently limited and documented to 40 ms, but the software does not check this.  |
| 2364 | Long Range TX packets          | Coded PHY TX packets are over-deviating, causing possible IOP issues.  |

### Bluetooth Smart Software 2.3.2 build 2263

| <b>Software Version</b> | 2.3.2 build 2263  |
|-------------------------|---|
| Software Status         | GA  |
| Release Date            | 26th of May, 2017   |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>BGM121 Bluetooth Smart Module<br>EFR32BG1 Blue Gecko<br>EFR32BG12 Blue Gecko<br>EFR32MG1 Mighty Gecko<br>EFR32MG12 Mighty Gecko |

## Changes: 2.3.2 (build 2263) compared to 2.3.1 (build 2044)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note | Explanation |
|------|-------------|
| -    | _           |

#### **Quality Improvements**

API documentation improved

Interrupting OTA DFU does not brick the device anymore

*Bluetooth* 5 connection event is no longer raised when legacy API is used to open the connection Empty data buffer handling fixed in UART

RTCC overflow fixed, enabling also multiple soft timers to work correctly

Stack initialization no longer fails because of RTCC counter values

Stack no longer freezes when calling cmd\_gatt\_set\_characteristic\_notification() when the remote GATT server has been disconnected

Pairing timeout with Mac OS fixed by adding IRK for local device so bonded device can resolve the private address

Current consumption reduced when a connection is closed immediately after opening it BGTool fixed to build BGScript examples correctly

### Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID   | Issue                            | Explanation  |
|------|----------------------------------|--|
| 112  | le_gap_scan_response             | Event le_gap_scan_response does not contain advertising channel information.   |
| 194  | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247  | Connection update                | Connection update can fail if connection event is missed.  |
| 679  | HW Configurator                  | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 1248 | Prepare write request            | Prepare write request does not fail with gatt_prodecure_completed event if data is corrupted.  |
| 1487 | Bonding with 8 slaves            | 8th consecutive bonding by master device fails with multiple slaves.   |
| 1814 | IAR and GCC compiler             | One should not have both IAR and GCC toolchains active in Simplicity Studio when a new project is created. Otherwise the toolchain is automatically set to IAR, even if GCC was originally chosen. |

### Bluetooth Smart Software 2.3.1 build 2044

| <b>Software Version</b> | 2.3.1 build 2044  |
|-------------------------|---|
| Software Status         | GA  |
| Release Date            | 10th of April, 2017   |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>BGM121 Bluetooth Smart Module<br>EFR32BG1 Blue Gecko<br>EFR32BG12 Blue Gecko<br>EFR32MG1 Mighty Gecko<br>EFR32MG12 Mighty Gecko |

## Changes: 2.3.1 (build 2044) compared to 2.3.0 (build 1981)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note | Explanation |
|------|-------------|
| -    | -           |

#### **Quality Improvements**

Documentation updates

Thunderboard Sense example supports GCC as well

Fixed device reset which was caused by protocol timer wrap-around

Fixed device reset which was caused by overlapping DCDC settings when using high TX power Fixed DTM RX issue for EFR32[B|M]G12 products

Fixed RTCC timer overflow issue, which caused cmd\_hardware\_get\_time() command not to work correctly

Fixed in-place OTA feature to work correctly with secure boot and firmware image signing Fixed BTDS plug-ins for Simplicity Studio and IAR projects

Fixed OTA DFU for EFR32[B|M]G12 products with Gecko Bootloader (both with security enabled and with security disabled)

## Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID   | Issue                            | Explanation  |
|------|----------------------------------|--|
| 112  | le_gap_scan_response             | Event le_gap_scan_response does not contain advertising channel information.   |
| 194  | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247  | Connection update                | Connection update can fail if connection event is missed.  |
| 679  | HW Configurator                  | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 1248 | Prepare write request            | Prepare write request does not fail with gatt_prodecure_completed event if data is corrupted.  |
| 1487 | Bonding with 8 slaves            | 8th consecutive bonding by master device fails with multiple slaves.   |
| 1814 | IAR and GCC compiler             | One should not have both IAR and GCC toolchains active in Simplicity Studio when a new project is created. Otherwise the toolchain is automatically set to IAR, even if GCC was originally chosen. |

# Bluetooth Smart Software 2.3.0 build 1981

| <b>Software Version</b> | 2.3.0 build 1981  |
|-------------------------|---|
| Software Status         | GA  |
| Release Date            | 10th of March, 2017   |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>BGM121 Bluetooth Smart Module<br>EFR32BG1 Blue Gecko<br>EFR32BG12 Blue Gecko<br>EFR32MG1 Mighty Gecko<br>EFR32MG12 Mighty Gecko |

# Changes: 2.3.0 (build 1981) compared to 2.1.1 (build 1691)

### **New Features**

| Feature                        | Explanation   |
|--------------------------------|---|
| EFR32[B M]G12                  | Support for EFR32BG12 and EFR32MG12 product families with maximum 256 kB of RAM and maximum 1024 kB of flash added.   |
| 2M PHY                         | Implementation for <i>Bluetooth</i> 5 2M PHY feature added. Supported in EFR32BG12 and EFR32MG12 parts.   |
| Switched multiprotocol support | This SDK supports switched multiprotocol use cases with EFR32[B M]G12 parts, enabling switching between Bluetooth and mesh stacks at boot time and allowing data exchange between the stacks. For more information, please see UG267: Multiprotocol User Guide. |
| BGAPI command size             | BGAPI command size is fixed to the maximum size of 256 bytes in stand-alone and NCP modes.  |
| ATT MTU size                   | ATT MTU maximum size has been increased to 250 bytes.   |

| Feature                             | Explanation   |
|-------------------------------------|---|
| GCC compiler support                | This SDK release contains Beta level support for GCC compiler.  |
| Advertisement Sets                  | This release contains support for <i>Bluetooth</i> 5 Advertisement Sets feature.  |
| cmd_le_gap_bt5_set_adv_data()       | This command is the same as cmd_le_gap_set_adv_data, but it has been extended to support <i>Bluetooth</i> 5 advertisement sets feature.       |
| cmd_le_gap_bt5_set_adv_parameters() | This command is the same as cmd_le_gap_set_adv_parameters, but it has been extended to support <i>Bluetooth</i> 5 advertisement sets feature. |
| cmd_le_gap_bt5_set_mode()           | This command is the same as cmd_le_gap_set_mode, but it has been extended to support <i>Bluetooth</i> 5 advertisement sets feature.           |
| evt_le_connection_bt5_opened        | This event is the same as evt_le_connection_opened, but it has been extended to support <i>Bluetooth</i> 5 advertisement sets feature.        |
| evt_le_gap_scan_request             | This event reports any scan request received in advertisement mode if scan request reporting is enabled.                                      |
| enum_le_gap_adv_address_type        | Identity and non-resolvable advertisement address types added.  |
| cmd_system_halt()                   | This command forces radio to idle state and allows device to sleep. Advertising, scanning, connections and software timers are also halted.   |

## Notes

| Note                  | Explanation   |
|-----------------------|---|
| Studio version update | This SDK is compliant with Simplicity Studio 4.11 or newer. |

| Note                                    | Explanation   |
|---|---|
| Simplicity<br>Commander                 | This SDK is compliant with Simplicity Commander 0.22.1 or newer.  |
| Gecko<br>Bootloader                     | This SDK contains support for the new Gecko Bootloader, supporting also secure DFU. For Bluetooth SDK, Gecko Bootloader is the only supported bootloader for EFR32[B M]G12 product families for now on. For EFR32[B M]G1 product families, the legacy OTA and UART bootloaders are also supported still. More information about the new bootloader can be found from UG266: Silicon Labs Gecko Bootloader User Guide.   |
| bgapi.a                                 | All applications using BGAPI must now be linked with bgapi.a library.   |
| DTM extensions                          | <ul> <li>New parameter phy added to the following DTM commands:</li> <li>test_dtm_rx(channel) =&gt; test_dtm_rx(channel, phy)</li> <li>test_dtm_tx(packet_type, length, channel) =&gt; test_dtm_tx(packet_type, length, channel, phy)</li> <li>Using test_phy_1m as the phy parameter value will produce the same behavior as before.</li> </ul>  |
| Crypto cores                            | EFR32[B M]G12 product family supports two crypto cores. Core 0 is always used by the <i>Bluetooth</i> stack, leaving core 1 for the application.  |
| BRD4156A and<br>BRD4157B                | These radio boards are no longer supported by this SDK. These are replaced by BRD4164A and BRD4163A.  |
| BGScript with<br>EFR32[B M]G12          | BGScript is no longer supported in these product families.  |
| BGScript<br>changes for<br>EFR32[B M]G1 | The following commands and events have changed to comply with the new features and improvements, and user applications must be changed accordingly.  • sent_len parameter added to the response message:  o gatt_prepare_characteristic_value_write(connection, characteristic, offset, value_len, value_data)(result, sent_len)  o gatt_write_characteristic_value_without_response(connection, characteristic, value_len, value_data)(result, sent_len)  o gatt_server_send_user_read_response(connection, characteristic, att_errorcode, value_len, value_data)(result, sent_len)  o gatt_server_send_characteristic_notification(connection, characteristic, value_len, value_data)(result, sent_len)  max_mtu parameter added to the response message:  o gatt_set_max_mtu(max_mtu)(result, max_mtu) |

| Note  | Explanation  |
|---|--|
|   | <ul> <li>txsize (maximum Data Channel PDU payload size the controller can send in an air packet) parameter has been added to le_connection_parameter event</li> <li>le_connection_parameters(connection, interval, latency, timeout, security_mode, txsize)</li> </ul>   |
| BGScript deprecation                              | BGScript support, also in EFR32[B M]G1 products, will be discontinued in the next major release.   |
| BGAPI HW, flash and utilities command deprecation | The following BGAPI commands will be deprecated in the next major release:  cmd_flash_ps_dump()  cmd_flash_ps_erase_all()  cmd_flash_ps_save()  cmd_flash_ps_load()  cmd_flash_ps_erase()  cmd_hardware_config_adc_reference()  cmd_hardware_configure_gpio()  cmd_hardware_enable_dcdc()  cmd_hardware_read_adc()  cmd_hardware_read_adc_channel()  cmd_hardware_read_gpio()  cmd_hardware_read_i2c()  cmd_hardware_set_uart_configuration()  cmd_hardware_write_gpio()  cmd_hardware_write_i2c()  cmd_util_atoi()  cmd_util_atoi()  cmd_util_atoi()  The following BGAPI events will be deprecated in the next major release:  evt_hardware_interrupt  The following BGAPI enumerations will be deprecated in the next major release:  enum_hardware_adc_channel  enum_hardware_adc_reference  enum_hardware_adc_reference  enum_hardware_uartparity |

# **Quality Improvements**

Documentation updates

Example applications and demos ported also to the new products

Link layer packet size increased to 128 bytes

LEUART functionality verified

HCI packet handling improved

When using OTA DFU, firmware size is pre-checked prior to writing it to flash

Thunderboard Sense demo added to the SDK

Data corruption prevented in BGAPI by making the API level data checks more robust

GATT local database now supports attribute value and user-handled characteristic length up to 512 bytes

GATT compiler and parser, handling gatt.xml files, have been improved

DTM updated to comply with new Bluetooth 5 features

Maximum number of stored bondings have been increased to 14

Memory overflows prevented in internal memory handling

Connection closed events are no longer lost, even if the connection is lost in the middle of bonding

Scan response handling improved

GATT server memory overflow fixed

ATT level buffer handling improved

Windows 10 interoperability improved

gatt\_prepare\_characteristic\_value\_write command does not anymore silently discard too long data

BGTool updated to comply with new *Bluetooth* 5 features

Data size is now reported within le\_connection\_parameters event for better application level throughput optimization

J-Link interface changed from JTAG to SWD for the legacy bootloader IAR project to enable bootloader code debugging

OTA DFU can now utilize larger ATT MTU size for better throughput

Visual GATT Editor updated

Security Manager robustness improvements

#### **Fixed Known Issues since the previous Release**

| ID   | Issue                                  | Explanation  |
|------|--|--|
| 681  | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes.   |
| 1431 | gap_set_mode()                         | The command does not return an error if<br>the device is being set to connectable<br>mode and the maximum number of<br>connections has been reached. |

| ID   | Issue         | Explanation  |
|------|---------------|--|
| 1432 | le_gap_open() | The command stalls if device is advertising as connectable and has reached max_connections – 1.        |
| 1445 | ATT MTU size  | To avoid a possible memory overflow in BGAPI, the maximum ATT MTU size should be limited to 121 bytes. |

| ID   | Issue                            | Explanation  |
|------|----------------------------------|--|
| 112  | le_gap_scan_response             | Event le_gap_scan_response does not contain advertising channel information.   |
| 194  | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247  | Connection update                | Connection update can fail if connection event is missed.  |
| 679  | HW Configurator                  | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 1248 | Prepare write request            | Prepare write request does not fail with gatt_prodecure_completed event if data is corrupted.  |
| 1487 | Bonding with 8 slaves            | 8th consecutive bonding by master device fails with multiple slaves.   |
| 1814 | IAR and GCC compiler             | One should not have both IAR and GCC toolchains active in Simplicity Studio when a new project is created. Otherwise the toolchain is automatically set to IAR, even if GCC was originally chosen. |

## Bluetooth Smart Software 2.1.1 build 1691

| Software Version  | 2.1.1 build 1691  |
|-------------------|---|
| Software Status   | GA  |
| Release Date      | 21st of December, 2016  |
| Affected Products | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>BGM121 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 2.1.1 (build 1691) compared to 2.1.0 (build 1638)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note | Explanation |
|------|-------------|
| -    | -           |

#### **Quality Improvements**

Fixed a memory leak in pairing procedure using secure connections Fixed a firmware update issue, which prevented updating the software from 2.0.x version to 2.1.x version

Fixed BGTool Commander path in OS X version of the SDK Removed obsolete 2.0.x SDK documentation

### Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID   | Issue                                  | Explanation  |
|------|--|--|
| 112  | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194  | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247  | Connection update                      | Connection update can fail if connection event is missed.  |
| 679  | HW Configurator                        | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 681  | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. The limitation is now properly documented, but the root cause has not been fixed yet in this release. |
| 1248 | Prepare write request                  | Prepare write request does not fail with gatt_prodecure_completed event if data is corrupted.  |
| 1431 | gap_set_mode()                         | The command does not return an error if the device is being set to connectable mode and the maximum number of connections has been reached.  |
| 1432 | le_gap_open()                          | The command stalls if device is advertising as connectable and has reached max_connections – 1.  |
| 1445 | ATT MTU size                           | To avoid a possible memory overflow in BGAPI, the maximum ATT MTU size should be limited to 121 bytes.   |

## Bluetooth Smart Software 2.0.3 build 1690

| Software Version  | 2.0.3 build 1690  |
|-------------------|---|
| Software Status   | GA  |
| Release Date      | 21st of December, 2016  |
| Affected Products | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>BGM121 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 2.0.3 (build 1690) compared to 2.0.2 (build 1604)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note | Explanation |
|------|-------------|
| -    | -           |

#### **Quality Improvements**

Fixed a memory leak in pairing procedure using secure connections Fixed a firmware update issue, which prevented updating the software from 2.0.x version to 2.1.x version

### **Fixed Known Issues since the previous Release**

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID  | Issue                                  | Explanation  |
|-----|--|--|
| 112 | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194 | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247 | Connection update                      | Connection update can fail if connection event is missed.  |
| 679 | HW Configurator                        | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 681 | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. The limitation is now properly documented, but the root cause has not been fixed yet in this release. |

# Bluetooth Smart Software 2.1.0 build 1638

| Software Version  | 2.1.0 build 1638  |
|-------------------|---|
| Software Status   | GA  |
| Release Date      | 5th of December, 2016   |
| Affected Products | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>BGM121 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 2.1.0 (build 1638) compared to 2.0.0 (build 1391)

### **New Features**

| Feature               | Explanation   |
|-----------------------|---|
| ATT MTU size increase | Attribute Protocol MTU maximum size is now 126 bytes.   |
| Graphical GATT Editor | This new tool helps to automatically generate a GATT database based on user selections. It supports all <i>Bluetooth</i> profiles, services and characteristics.  |
| Apple HomeKit         | This SDK has the necessary enablers in place to support Apple HomeKit R7 compliant software development. Please see <a href="http://www.silabs.com/homekit">http://www.silabs.com/homekit</a> to get started. |
| OOB pairing           | Out of band pairing is now supported for secure connections.  |

#### **Notes**

| Note                  | Explanation  |
|-----------------------|--|
| Studio version update | SDK is compliant with Simplicity Studio 4.06 or newer.   |
| Bootloader            | Bootloader has been updated. Details of the changes are described in a Knowledge Base article: <a href="http://community.silabs.com/t5/Bluetooth-Wi-Fi-Knowledge-Base/Bootloader-changes-in-BLE-SDK/ta-p/183640">http://community.silabs.com/t5/Bluetooth-Wi-Fi-Knowledge-Base/Bootloader-changes-in-BLE-SDK/ta-p/183640</a> |

| Note            | Explanation   |
|-----------------|---|
| IAR version     | In <i>Bluetooth</i> C development, one should have IAR version 7.80.2 or newer in use.  |
| Migration guide | For easier migration from 2.0.x SDK to this one, there is a Knowledge Base article available: <a href="http://community.silabs.com/t5/Bluetooth-Wi-Fi-Knowledge-Base/Bluetooth-Smart-SDK-Migration-Guide-From-V2-0-1-to-V2-1-x/ta-p/183921">http://community.silabs.com/t5/Bluetooth-Wi-Fi-Knowledge-Base/Bluetooth-Smart-SDK-Migration-Guide-From-V2-0-1-to-V2-1-x/ta-p/183921</a> |

#### **Quality Improvements**

Fix for maximum input signal level (TP/RCV-LE/CA/BV-06-C) test by adjusting automatic gain control levels of the PA

Thunderboard React application improved

Simplicity Commander updated to 0.17.3 version, which generates properly formatted EBL firmware update files

Thunderboard Sense software example updated

Random number generator is now initialized properly at boot time

DTM fixed to also generate unmodulated carrier properly using the test command

BGTool updated

BTDS plug-ins updated

CRC check added to OTA firmware update

UART bootloader error reporting improved

DTM example application added

Documentation updated

Added AN1045: Bluetooth Over-the-Air Device Firmware Update Application Note

Length parameter calculated correctly for commands in NCP mode

BGAPI command size maximum (128 bytes) is now the same for SoC and NCP modes

BGAPI command payload overflow does not cause a crash anymore

DTM does not stop listening for new packets after 4 seconds anymore

Fixed waking up from EM4H mode by fixing DFU update request checking

Fixed Thermometer example for BGM121

Fixed OTA image size checking

BGAPI command handling improved to notify the user if the number of available buffers is too small

API documentation improved and updated

MITM protection works now also when slave device requests it

Slave device behavior fixed, when master device loses bonding

#### Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID   | Issue                                  | Explanation  |
|------|--|--|
| 112  | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194  | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247  | Connection update                      | Connection update can fail if connection event is missed.  |
| 679  | HW Configurator                        | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 681  | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. The limitation is now properly documented, but the root cause has not been fixed yet in this release. |
| 1248 | Prepare write request                  | Prepare write request does not fail with gatt_prodecure_completed event if data is corrupted.  |
| 1431 | gap_set_mode()                         | The command does not return an error if the device is being set to connectable mode and the maximum number of connections has been reached.  |
| 1432 | le_gap_open()                          | The command stalls if device is advertising as connectable and has reached max_connections – 1.  |
| 1445 | ATT MTU size                           | To avoid a possible memory overflow in BGAPI, the maximum ATT MTU size should be limited to 121 bytes.   |

## Bluetooth Smart Software 2.0.2 build 1604

| <b>Software Version</b> | 2.0.2 build 1604   |
|-------------------------|--|
| Software Status         | GA   |
| Release Date            | 25th of November, 2016   |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 2.0.2 (build 1604) compared to 2.0.1 (build 1485)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note | Explanation |
|------|-------------|
| -    | -           |

### **Quality Improvements**

Fix for maximum input signal level (TP/RCV-LE/CA/BV-06-C) test by adjusting automatic gain control levels of the PA.

Thunderboard React application improved.

### **Fixed Known Issues since the previous Release**

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID  | Issue                                  | Explanation  |
|-----|--|--|
| 112 | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194 | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247 | Connection update                      | Connection update can fail if connection event is missed.  |
| 679 | HW Configurator                        | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 681 | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. The limitation is now properly documented, but the root cause has not been fixed yet in this release. |

### Bluetooth Smart Software 2.0.1 build 1485

| <b>Software Version</b> | 2.0.1 build 1485   |
|-------------------------|--|
| Software Status         | GA   |
| Release Date            | 15th of October, 2016  |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 2.0.1 (build 1485) compared to 2.0.0 (build 1391)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note | Explanation |
|------|-------------|
| -    | -           |

### **Quality Improvements**

Simplicity Commander updated to 0.17.3 version, which generates properly formatted EBL firmware update files. Workaround for the original issue in 2.0.0 GA is described in <a href="http://community.silabs.com/t5/Bluetooth-Wi-Fi-Knowledge-Base/Testing-UART-DFU-with-BLE-SDK-2-0-0-1391/ta-p/179823">http://community.silabs.com/t5/Bluetooth-Wi-Fi-Knowledge-Base/Testing-UART-DFU-with-BLE-SDK-2-0-0-1391/ta-p/179823</a>.

Thunderboard Sense software example updated Random number generator is now initialized properly at boot time DTM fixed to also generate unmodulated carrier properly using the test command

### Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID  | Issue                                  | Explanation  |
|-----|--|--|
| 112 | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194 | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247 | Connection update                      | Connection update can fail if connection event is missed.  |
| 679 | HW Configurator                        | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 681 | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. The limitation is now properly documented, but the root cause has not been fixed yet in this release. |

## Bluetooth Smart Software 2.0.0 build 1391

| <b>Software Version</b> | 2.0.0 build 1391   |
|-------------------------|--|
| Software Status         | GA   |
| Release Date            | 16th of September, 2016  |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 2.0.0 (build 1391) compared to 2.0.0 (build 1353)

#### **New Features**

| Feature | Explanation |
|---------|-------------|
| -       | -           |

#### **Notes**

| Note          | Explanation   |
|---------------|---|
| Version 1.0.x | Version 2.0.0 is not backwards compatible with 1.0.x versions, meaning that an application written with 1.0.x SDK, will not work without modifications in 2.0.0 SDK and vice versa. Additionally, one cannot perform DFU, either over UART nor OTA, between the versions 1.0.x and 2.0.0. |
| BGM111v1.0    | The first HW version (v1.0) of the BGM111 Bluetooth module is no longer supported in Simplicity Studio v4.  |

### **Quality Improvements**

Examples and demos updated

Documentation updated

BGTool and bgbuild tools updated

SW flow control added to UART DFU functionality

DFU robustness improved by fixing buffer overflow situations

DFU CRC checksum calculation added

GATT parser in bgbuild warns the user if << gatt service>> is not the first defined service

Bootloader IAR example application added to SDK Data packet handling robustness improved to avoid possible deadlock situations in memory buffer allocation

## Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
| -  | -     | -           |

| ID  | Issue                                  | Explanation  |
|-----|--|--|
| 112 | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194 | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247 | Connection update                      | Connection update can fail if connection event is missed.  |
| 679 | HW Configurator                        | HW Configurator in Simplicity Studio v4 does not currently allow changing some of the HW settings like for example DCDC, LFXO, and CTUNE values.   |
| 681 | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. The limitation is now properly documented, but the root cause has not been fixed yet in this release. |

# Bluetooth Smart Software 2.0.0 build 1353

| <b>Software Version</b> | 2.0.0 build 1353   |
|-------------------------|--|
| Software Status         | Beta   |
| Release Date            | 2nd of September, 2016   |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

# Changes: 2.0.0 (build 1353) compared to 1.0.4 (build 1073)

### **New Features**

| Feature              | Explanation   |
|----------------------|---|
| Secure Connections   | Support for LE Secure Connections according to <i>Bluetooth</i> specification 4.2. Including ECDH key exchange and passkey comparison with MITM. When communicating with legacy devices, the implementation will fall back to 4.0 pairing.  |
| Packet Extensions    | First implementation for increasing the link layer packet size according to <i>Bluetooth</i> specification 4.2. This release supports link layer packet size up to 50 bytes instead of the default 23 bytes.  |
| Dual Topology        | Support for Dual Topology according to <i>Bluetooth</i> specification 4.1. This enables EFR32 to be a slave and master device at the same time.   |
| Simplicity Studio v4 | This build and corresponding SDK is compatible with Simplicity Studio v4. This enables for example having multiple SDKs installed at the same time, and creating for example IAR and BGScript projects in a single SDK. Earlier Simplicity Studio version 3 is no longer supported. Also former |

| Feature                                      | Explanation  |
|--|--|
|  | "Blue Gecko Bluetooth Smart BGScript and IAR SDK 1.0.x" is discontinued.   |
| BTDS plug-ins                                | This SDK build includes plug-ins, which can be used to quickly and efficiently create consistent Bluetooth profiles and applications using <i>Bluetooth</i> Developer Studio tool, developed by <i>Bluetooth</i> SIG.      |
| sm_bonding_confirm()                         | This command is used to accept or reject a bonding request. A new bonding request is indicated by a corresponding sm_confirm_bonding event.  |
| sm_passkey_confirm()                         | This command is used to accept or reject a reported confirm value. Corresponding event to indicate the request to display the passkey to the user and for the user to confirm the displayed passkey is sm_confirm_passkey. |
| sm_set_debug_mode()                          | This command is used to set Security Manager into debug mode, enabling encrypted packets to be opened with a Bluetooth protocol analyzer as the secure connections are using debug keys for bonding.                       |
| dfu_boot_failure event                       | This event indicates that there has been an error in bootloader and the reason is given as an error code.  |
| gatt_read_characteristic_value_from_offset() | This command can be used to read a partial characteristic value from a remote GATT database with specified offset and maximum length.  |

# Notes

| Note        | Explanation  |  |
|-------------|--|--|
| IAR version | In <i>Bluetooth</i> C development, one should have IAR version 7.60 or newer in use. |  |

| Note                   | Explanation  |  |
|------------------------|--|--|
| Bootloader             | Bootloader library is now separated from the stack library, and the bootloader itself has been updated as well. Application now needs to link the new bootloader library as well as include aat.h file. Please see UG136 document for details. |  |
| UART and OTA<br>DFU    | UART and OTA DFU binary files have been updated to be in EBL format. Simplicity Commander, included into SDK, can be used to flash devices. Please see UG136 document for details.   |  |
| BGAPI library          | BGAPI library is now separated from the stack library. It must be linked with the application if BGAPI commands are tend to be used. Please see UG136 document for details.  |  |
| endpoint_closing event | This event is removed from the API documentation as it has been decided not to be implemented.   |  |

### **Quality Improvements**

Examples and demos updated and simplified
Documentation updated
BGTool and bgbuild tools updated
Robustness, timing and other quality fixes in link layer
Stack robustness improvements, especially in GAP, GATT and Security Manager
GATT database improvements
Fixed a memory leak in GATT server
Reduced power consumption for all use cases

### Fixed Known Issues since the previous Release

| ID  | Issue                            | Explanation  |
|-----|----------------------------------|--|
| 347 | BGScript freeze                  | BGScript freezes, when trying to store a PS key, which is longer than 180 bytes. |
| 495 | endpoint_read_counters()         | The command does not return correct data.  |
| 638 | sm_store_bonding_configuration() | The command returns an error, indicating that it is not implemented.             |

| ID  | Issue                                  | Explanation  |
|-----|--|--|
| 112 | le_gap_scan_response                   | Event le_gap_scan_response does not contain advertising channel information.   |
| 194 | Connection update complete event       | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.  |
| 247 | Connection update                      | Connection update can fail if connection event is missed.  |
| 681 | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. Update: The limitation is now properly documented, but the root cause has not been fixed yet in this release. |

# Bluetooth Smart Software 1.0.4 build 1073

| <b>Software Version</b> | 1.0.4 build 1073   |
|-------------------------|--|
| Software Status         | GA 3   |
| Release Date            | 17th of June, 2016   |
| Affected Products       | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

# Changes: 1.0.4 (build 1073) compared to 1.0.2 (build 755)

### **New Features**

| Feature                        | Explanation   |
|--------------------------------|---|
| hardware_set_lazy_soft_timer() | BGAPI command to allow a sliding timer to be used to let the stack optimize wake-up times and save power. |
| hardware_enable_dcdc()         | BGAPI command to enable and disable DC/DC.  |

#### Notes

| Note                      | Explanation  |  |
|---------------------------|--|--|
| Qualification             | All official <i>Bluetooth</i> qualifications are completed.  |  |
| IAR version               | In <i>Bluetooth</i> C development, one should have IAR version 7.40 or newer in use.   |  |
| hardware_set_soft_timer() | Time parameter unit of this command has been now properly documented, and the maximum time value is approximately 18.2 hours (2147483647 clock ticks).   |  |
| Windows 10 / Edge         | Using Edge browser in Windows 10 to download <i>Bluetooth</i> Smart SDK for Simplicity Studio or Blue Gecko <i>Bluetooth</i> Smart BGScript and IAR SDK will result an error note "The signature of <exe file="" name=""> is corrupt or invalid." The file is still fully downloaded and the SDK can be installed.</exe> |  |

### **Quality Improvements**

Examples and demos updated

Documentation updated

BGTool and bgbuild tools updated and Linux and Mac OS compatibility improved

UART DFU and OTA DFU work correctly even if PTI is enabled

Stack and link layer robustness improvements

EM2 sleep wake-up time reduced to save power

Advertising power consumption reduced

RAM consumption optimizations and enabling more dynamic memory allocation for applications

Android and iOS interoperability improved

Connection update request instant value fixed

Advertising functionality optimizations

#### Fixed Known Issues since the previous Release

| ID | Issue | Explanation |
|----|-------|-------------|
|    |       |             |

| ID  | Issue                            | Explanation   |
|-----|----------------------------------|---|
| 112 | le_gap_scan_response             | Event le_gap_scan_response does not contain advertising channel information.  |
| 194 | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event. |
| 247 | Connection update                | Description updated: Connection update can fail if connection event is missed.  |
| 347 | BGScript freeze                  | BGScript freezes, when trying to store a PS key, which is longer than 180 bytes.  |
| 495 | endpoint_read_counters()         | The command does not return correct data.   |
| 638 | sm_store_bonding_configuration() | The command returns an error, indicating that it is not implemented.  |

| ID  | Issue                                  | Explanation  |
|-----|--|--|
| 681 | gatt_server_send_user_write_response() | If a user application tries to send a user write response greater than 128 bytes, the stack crashes. |

# **Bluetooth** Smart Software 1.0.2 build 755

| Software Version  | 1.0.2 build 755  |
|-------------------|--|
| Software Status   | GA 2   |
| Release Date      | 29th of March, 2016  |
| Affected Products | BGM111 Bluetooth Smart Module<br>BGM113 Bluetooth Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

# Changes: 1.0.2 (build 755) compared to 1.0.0 (build 615)

### **New Features**

| Feature                           | Explanation   |
|-----------------------------------|---|
| BGM113                            | Support and examples for BGM113 <i>Bluetooth</i> Smart Module added.  |
| Qualification                     | All controller and host side qualification test are run and passed. Official <i>Bluetooth</i> listings are still pending. |
| RX/TX activity PIN                | Possibility to observe RX/TX activity by using <obssel> tag in hardware.xml file.</obssel>                                |
| ATT MTU size increase             | Attribute Protocol MTU size can be increased up to 58 bytes.  |
| system_get_random_data()          | BGAPI command to get random data up to 16 bytes.  |
| sm_set_oob_data()                 | BGAPI command to set out of band encryption data for the device.  |
| sm_confirm_passkey event          | New event to indicate a request to display the passkey to the user and the user to confirm it.                            |
| hardware_set_uart_configuration() | BGAPI command to configure UART interface.  |
| hardware_get_time()               | BGAPI command to get elapsed time since last reset of RTCC.   |
| hardware_read_adc_channel()       | BGAPI command to read a specific ADC channel.   |

| Feature                  | Explanation  |
|--------------------------|--|
| gatt_set_max_mtu()       | BGAPI command to set maximum number of GATT message transfer units.  |
| gatt_mtu_exchanged event | New event to indicate that GATT exchange procedure has been completed.   |
| sm_configure()           | sm_configure command parameter mitm_required is renamed to flags for accepting more security configurations, namely bonding_required |

#### **Quality Improvements**

Examples and demos updated

Documentation updated

BGTool and other tools updated and OS X support improved

Master and slave can now increase security at the same time without other one becoming unresponsive

UART communication works reliably also for 2.4M and above baud rates

Scanning and advertising fixed to work at the same time

Improved event listening according to the transmit window setting

Improved Android OS interoperability

Memory usage optimizations for BGScript and TX queue

Memory leak fix for UART configuration

Fix for GATT client to handle long attribute data fully

Fix le\_gap\_set\_mode() command to also restart advertising properly

Fix disable advertising to immediately also stop advertising

Robustness fixes for validating and updating advertisement data

Optimizations for startup time when waking up before advertising to save current

Access address error fixed

Current consumption optimizations for DTM, NCP mode and advertising

Memory leak fixed in scan response handling

Multi-connection error situation handling improved

DFU improvements

#### Fixed Known Issues since the previous Release

| ID  | Issue         | Explanation   |
|-----|---------------|---|
| 172 | Notifications | If the devices are bonded, and then disconnected, reconnected and the connection is encrypted, no gatt_server_characteristic_status event is sent to let user know if the notifications have been enabled or not. |

| ID  | Issue                              | Explanation  |
|-----|------------------------------------|--|
| 195 | ATT MTU size                       | ATT MTU size is limited to its default value (23).   |
| 197 | hardware_set_soft_timer()          | Using hardware_set_soft_timer() with very small timeout parameter, like 1, will cause a crash.   |
| 199 | Channel map request                | If channel map request handling takes too long time, the connection is terminated.   |
| 223 | TX power in ADV data               | Even if TX power has been set with system_set_tx_power() command, it is always 0 dBm in advertisement data.  |
| 226 | gatt_characteristic_value<br>event | Even if gatt_prepare_characteristic_value_write() command succeeds, sometimes gatt_characteristic_value event is not returned.   |
| 254 | Scanning events                    | Scanning for new devices in master mode does not work or it takes a long time if a lot of connections are active and connection interval has been defined to be very small.                                  |
| 277 | hardware_set_soft_timer()          | API Reference Manual says that timer value parameter unit should be given in milliseconds, but actually the value should be given in clock ticks, which are 1/32768 of a millisecond.                        |
| 312 | BGScript reconnect                 | If the device is changing its advertising as non-<br>connectable while being connected, after<br>disconnection it cannot reconnect, when BGScript<br>application is used. This works OK when using<br>BGAPI. |
| 323 | TX power steps                     | There are no intermediate TX power steps between - 12.5 dBm and -26 dBm TX power settings.   |

| ID  | Issue                | Explanation  |
|-----|----------------------|--|
| 112 | le_gap_scan_response | Event le_gap_scan_response does not contain advertising channel information. |

| ID  | Issue                            | Explanation   |
|-----|----------------------------------|---|
| 194 | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event. |
| 247 | Connection update                | Connection event can be missed if it happens at the same time as a connection update.   |
| 347 | BGScript freeze                  | BGScript freezes, when trying to store a PS key, which is longer than 180 bytes.  |

## Bluetooth Smart Software 1.0.0 build 615

| Software Version  | 1.0.0 build 615  |
|-------------------|--|
| Software Status   | GA 1   |
| Release Date      | 20th of February, 2016   |
| Affected Products | BGM111 <i>Bluetooth</i> Smart Module<br>EFR32 Blue Gecko<br>EFR32 Mighty Gecko |

## Changes: 1.0.0 (build 615) compared to 0.9.2 (build 446)

#### **New Features**

| Feature                               | Explanation   |
|---------------------------------------|---|
| gatt_server_find_attribute()          | New command to find attributes of certain type from a local GATT database.  |
| le_connection_disable_slave_latency() | Device in slave mode can temporarily disable/enable slave latency.  |
| Host wake-up PIN support              | Support for PIN configuration, which can be used to wake up external host processor.  |
| OTA firmware update (internal flash)  | Over The Air firmware update has been enabled in<br>the stack. However, there is no automatic code<br>generating for this feature yet in Simplicity Studio.   |
| Bluetooth Low Energy C SDK            | Necessary changes and implementation for integrating <i>Bluetooth</i> Smart Software with <i>Bluetooth</i> Low Energy C SDK in Simplicity Studio, supporting the usage of many other tools there as well. |

### **Quality Improvements**

Examples and demos updated
Documentation updated
Multi-connection robustness improvements
Lowest TX power setting is now -26 dBm instead of -12.5 dBm
Memory usage optimizations

Memory leak fixes

Multiple SW crashes fixed

PTI configuration structure fixed to enable packet trace debugging with Simplicity Studio Improved interoperability with the latest iOS and Android devices

Updates and bug fixes for BGTool PC SW, now integrated also with Simplicity Studio Slave latency feature fixed

Sequencer and scheduler optimizations and fixes to improve connection robustness

Bonding robustness fixes related to master and slave modes

Improvements in UART handling

Sleep optimizations for applications

Updates and improvements to DFU handling

Updates to Security Manager robustness and optimizations

Channel map handling improvements

GATT parser robustness improvements

Robustness improvements for scanning and advertising functionality

BGAPI improvements for sleep mode

#### **Fixed Known Issues since the previous Release**

| ID  | Issue                   | Explanation   |
|-----|-------------------------|---|
| 113 | 128-bit service<br>UUID | Automatic 128-bit service UUID advertising does not work using le_gap_set_mode() command. Workaround is to use custom advertisement packet content and build it manually. |
| 146 | Encrypted data transfer | Sending a lot of data over encrypted link to both directions will eventually fail.  |
| 164 | Bonding timeout         | When both devices have been set in bondable mode and master increases security and also latency value is set, bonding fails with 0x185 (timeout).                         |
| 177 | Multiple connections    | Master cannot form multiple connections if the lowest possible connection interval is used. Workaround is to use other values.  |
| 180 | Connection counter      | LLCP Connection Update Request can cause connection counter to go out of sync, resulting the connection to be dropped.  |
| 185 | Reconnection failure    | When a connection request packet is not fully sent, the connection request will be ignored and it will fail with 0x181 (wrong state) when reconnecting is attempted.      |
| 187 | LL_VERSION_IND          | When queried over the air, LL_VERSION_IND indicates <i>Bluetooth</i> version to be 4.0 instead of 4.1.  |

| ID  | Issue                  | Explanation  |
|-----|------------------------|--|
| 192 | Connection update      | When maximum connection interval is used and the stack is run in slave mode, it does not respond to connection update requests.            |
| 196 | LL_PING bit            | LL_PING bit is not ignored properly between two controllers.   |
| 207 | Bonding initialization | If the lowest connection interval is used and bonding is initialized, connection is closed.  |
| 208 | GATT timeout           | Random GATT timeouts are seen with multiple simultaneous connections.  |
| 212 | Slave latency 1        | When the stack is in slave mode and slave latency is used, connection update will cause supervision timeout, and the connection is closed. |
| 228 | Slave latency 2        | Setting slave latency value to 0 after it has been set to a higher value, will cause connection failure.                                   |

| ID  | Issue                            | Explanation   |
|-----|----------------------------------|---|
| 112 | le_gap_scan_response             | Event le_gap_scan_response does not contain advertising channel information.  |
| 172 | Notifications                    | If the devices are bonded, and then disconnected, reconnected and the connection is encrypted, no gatt_server_characteristic_status event is sent to let user know if the notifications have been enabled or not. |
| 194 | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.   |
| 195 | ATT MTU size                     | ATT MTU size is limited to its default value (23).  |
| 197 | hardware_set_soft_timer()        | Using hardware_set_soft_timer() with very small timeout parameter, like 1, will cause a crash.  |
| 199 | Channel map request              | If channel map request handling takes too long time, the connection is terminated.  |

| ID  | Issue                           | Explanation  |
|-----|---------------------------------|--|
| 223 | TX power in ADV data            | Even if TX power has been set with system_set_tx_power() command, it is always 0 dBm in advertisement data.  |
| 226 | gatt_characteristic_value event | Even if gatt_prepare_characteristic_value_write() command succeeds, sometimes gatt_characteristic_value event is not returned.   |
| 247 | Connection update               | Connection event can be missed if it happens at the same time as a connection update.  |
| 254 | Scanning events                 | Scanning for new devices in master mode does not work or it takes a long time if a lot of connections are active and connection interval has been defined to be very small.  |
| 277 | hardware_set_soft_timer()       | API Reference Manual says that timer value parameter unit should be given in milliseconds, but actually the value should be given in clock ticks, which are 1/32768 of a millisecond.  |
| 312 | BGScript reconnect              | If the device is changing its advertising as non-<br>connectable while being connected, after disconnection<br>it cannot reconnect, when BGScript application is used.<br>This works OK when using BGAPI.  |
| 323 | TX power steps                  | There are no intermediate TX power steps between - 12.5 dBm and -26 dBm TX power settings.   |
| N/A | Qualification                   | The following qualification test cases do not pass yet: TC/JW/BV-02-C TC/CN/BV-01-C TC/CN/BV-02-C TP/CON/MAS/BV-30-C TP/CON/MAS/BV-29-C TP/CON/MAS/BI-05-C TP/CON/SLA/BV-22-C TP/SEC/MAS/BV-14-C TP/CON/SLA/BV-23-C TP/CON/SLA/BV-23-C TP/CON/SLA/BI-06-C TP/SEC/MAS/BV-12-C TP/SEC/MAS/BV-13-C TP/DDI/ADV/BV-19-C |

## Bluetooth Smart Software 0.9.2 build 446

| <b>Software Version</b>  | 0.9.2 build 446               |
|--------------------------|-------------------------------|
| Software Status          | Beta 2                        |
| Release Date             | 18th of December, 2015        |
| <b>Affected Products</b> | BGM111 Bluetooth Smart Module |

### Changes: 0.9.2 (build 446) compared to 0.9.1 (build 136)

#### **New Features**

| Feature                  | Explanation   |
|--------------------------|---|
| Energy Mode 2            | Energy Mode 2 (EM2) support added for lower current consumption when sleeping               |
| le_connection_get_rssi() | le_connection_get_rssi() command added to BGAPI   |
| ADC commands             | hardware_config_adc_reference() and hardware_read_adc() commands added to BGAPI             |
| system_set_tx_power()    | system_set_tx_power() command added to BGAPI  |
| LFXO configuration       | LFXO usage is made configurable in hardware.xml   |
| Wake-up PIN              | Wake-up PIN is made configurable in hardware.xml and gecko_system_awake event is introduced |
| DTM                      | Direct Test Mode tests implemented  |
| PTI                      | Packet trace / Network Analyzer enablers added for Simplicity Studio                        |

### **Quality Improvements**

SDK examples updated

Documentation updated

No need to reset the device anymore between DTM tests

Default maximum amount of simultaneous connections is set to four and the value is made configurable up to eight

Support for adding external BGAPI commands added

Multiple repeating soft timers enabled for BGScript

Correct power amplifier is dynamically chosen based on TX power setting

ADC conversion waiting bit fixed

Default output power is set to 8 dBm

EM2 wake-up timings optimized

MIC failures fixed to improve secure connection robustness

HCI advertisement event fixed

Many out of memory fixes

Many memory leaks fixed

Many memory allocation optimizations

Encrypted streaming data lost fixed

Possible flash write error handled properly

Fixed RTCC usage

UART timeout interrupt removed when the device is inactive

HCI reset commands fixed

New ACL queues for link layer implemented

Crystal tuning value handling fixed

Flow control fixed for sending multiple notifications

Variable access fixed in BGScript

I2C timeouts fixed

Control packet bits fixed in HCI commands and ACL packets

HCI events do not miss data anymore

Correct dBm values used in TX power configuration

Missing IRQ flags added

Bonding fixed in slave mode and robustness increased

Create connection cancel command fixed

Scan response and advertisement handling fixed

Incoming data packet handling memory optimizations

Stack flash size optimizations

Connection close events do not randomly fail anymore

Connection events can be skipped without crashing

No link timeout errors anymore with iOS devices

TX and RX activity current consumption peaks fixed

Multiple connections in master mode fixed

Many crashes fixed

Connection parameter update does not cause connection failure anymore

Packet queueing for TX fixed for encrypted connections

Access address issues fixed for master mode

Instant checking with connection update and channel map request fixed

Endianness for connection encryption command fixed

LL\_FEATURE\_RSP packet fixed

Scan duty cycle fixed

Scan response events fixed

Window size fixed

Disconnecting from iOS devices works correctly

Device name is correctly advertised with iOS devices

Disconnecting a non-established connection does not break the next connection anymore General PTS failure fixes

le\_gap\_set\_adv\_data() fixed to show the correct scan response data

Consecutive bonding does not fail anymore after a failed pairing and bonding

Advertising while connected and advertising restart fixed

GPIO interrupts fixed

Connection parameter update parameter value is checked correctly

RSSI values fixed in scan responses

BGScript utility functions added

UART data transfer hang with multiple queued L2CAP packets fixed

### **Fixed Known Issues since the previous Release**

| ID  | Issue                       | Explanation  |
|-----|-----------------------------|--|
| 13  | Scanning and advertising    | Simultaneous scanning and advertising does not always work.                      |
| 16  | Bonding                     | Unauthenticated bonding might sometimes fail in slave mode.                      |
| 92  | Advertising restart         | Restarting advertising too quickly does not always work.                         |
| 101 | Connection parameter update | In slave mode, sometimes connection parameter update causes supervision timeout. |

| ID  | Issue                   | Explanation   |
|-----|-------------------------|---|
| 112 | le_gap_scan_response    | Event le_gap_scan_response does not contain advertising channel information.  |
| 113 | 128-bit service UUID    | Automatic 128-bit service UUID advertising does not work using le_gap_set_mode() command. Workaround is to use custom advertisement packet content and build it manually. |
| 146 | Encrypted data transfer | Sending a lot of data over encrypted link to both directions will eventually fail.  |
| 164 | Bonding timeout         | When both devices have been set in bondable mode and master increases security and also latency value is set, bonding fails with 0x185 (timeout).                         |

| ID  | Issue                            | Explanation   |
|-----|----------------------------------|---|
| 172 | Notifications                    | If the devices are bonded, and then disconnected, reconnected and the connection is encrypted, no gatt_server_characteristic_status event is sent to let user know if the notifications have been enabled or not. |
| 177 | Multiple connections             | Master cannot form multiple connections if the lowest possible connection interval is used. Workaround is to use other values.  |
| 180 | Connection counter               | LLCP Connection Update Request can cause connection counter to go out of sync, resulting the connection to be dropped.  |
| 185 | Reconnection failure             | When a connection request packet is not fully sent, the connection request will be ignored and it will fail with 0x181 (wrong state) when reconnecting is attempted.  |
| 187 | LL_VERSION_IND                   | When queried over the air, LL_VERSION_IND indicates <i>Bluetooth</i> version to be 4.0 instead of 4.1.  |
| 192 | Connection update                | When maximum connection interval is used and the stack is run in slave mode, it does not respond to connection update requests.   |
| 194 | Connection update complete event | If a connection parameter update request is rejected by a remote device, the reject reason is not correctly returned by connection update complete event.   |
| 195 | ATT MTU size                     | ATT MTU size is limited to its default value (23).  |
| 196 | LL_PING bit                      | LL_PING bit is not ignored properly between two controllers.  |
| 197 | hardware_set_soft_timer()        | Using hardware_set_soft_timer() with very small timeout parameter, like 1, will cause a crash.  |
| 199 | Channel map request              | If channel map request handling takes too long time, the connection is terminated.  |
| 207 | Bonding initialization           | If the lowest connection interval is used and bonding is initialized, connection is closed.   |
| 208 | GATT timeout                     | Random GATT timeouts are seen with multiple simultaneous connections.   |

| ID  | Issue                | Explanation  |
|-----|----------------------|--|
| 212 | Slave latency 1      | When the stack is in slave mode and slave latency is used, connection update will cause supervision timeout, and the connection is closed.   |
| 223 | TX power in ADV data | Even if TX power has been set with system_set_tx_power() command, it is always 0 dBm in advertisement data.  |
| 228 | Slave latency 2      | Setting slave latency value to 0 after it has been set to a higher value, will cause connection failure.   |
| N/A | Qualification        | The following qualification test cases do not pass yet: PTS: TC/JW/BV-02-C TP/CON/MAS/BV-30-C TP/CON/MAS/BV-29-C TP/CON/MAS/BI-05-C TP/CON/SLA/BV-22-C TP/SEC/MAS/BV-14-C TP/CON/SLA/BV-23-C TP/CON/SLA/BI-06-C TP/SEC/MAS/BV-12-C TP/SEC/MAS/BV-13-C TP/DDI/ADV/BV-19-C |

# Bluetooth Smart Software 0.9.1 build 136

| <b>Software Version</b>  | 0.9.1 build 136               |
|--------------------------|-------------------------------|
| Software Status          | Beta                          |
| Release Date             | 17th of August, 2015          |
| <b>Affected Products</b> | BGM111 Bluetooth Smart Module |

#### **Features in the First Release**

| Feature   | Explanation   |
|-----------|---|
| BLE 4.1   | Bluetooth Smart 4.1 compliant stack                     |
| ATT       | Attribute Profile                                       |
| GATT      | Generic Attribute Profile                               |
| GAP       | Generic Access Profile                                  |
| SMP       | Security Manager Protocol                               |
| BGAPITM   | Serial protocol API over UART for modem usage           |
| BGLIBTM   | Host API/library which implements BGAPI serial protocol |
| BGScript™ | Scripting language for standalone usage                 |

### Fixed Known Issues since the previous Release

| ID  | Feature | Explanation          |
|-----|---------|----------------------|
| N/A | N/A     | First public release |

| ID | Issue                    | Explanation   |
|----|--------------------------|---|
| 13 | Scanning and advertising | Simultaneous scanning and advertising does not always work. |

| ID  | Issue                       | Explanation  |
|-----|-----------------------------|--|
| 16  | Bonding                     | Unauthenticated bonding might sometimes fail in slave mode.                      |
| 92  | Advertising restart         | Restarting advertising too quickly does not always work.                         |
| 101 | Connection parameter update | In slave mode, sometimes connection parameter update causes supervision timeout. |